Submit 3 Copies o Appropriate District Office		Energy	erals and Natural R	lesources Department		Revined 1-1-89 C []
District of Res DISTRICT I P.O. Box 1980, Hobbs, NM 88240 DISTRICT II P.O. Drawer DD, Artesia, NM 88210		OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088		WELL API NO. 30-015-21566 5. Indicate Type of Lesse STATE FEE X		
						<u>DISTRICT III</u> 000 Rio Brazos Ra
	HIS FORM FOR PRO DIFFERENT RESEF	OPOSALS TO RVOIR. USE	REPORTS ON WE DRILL OR TO DEEPE "APPLICATION FOR PI UCH PROPOSALS.)	N OR PLUG BACK TO A		Unit Agreement Name Gas Com. #1
. Type of Well: Oll. WELL	GAS WELL		OTHER			
Name of Operat Whiting	Petroleum Cor	poration	n		8. Well No.	1
Address of Ope	nior			1-2301	9. Pool name or V E. Carlsba	
Well Location	adway, Suite	2300, D	enver, CO 80290		, t . <u></u>	
Unit Lette	r: <u>1980</u>) Feet Fro	m The South	Line and660	Feet From	n The West Line
	25	Townshi	in 215 i	ange 27E	NMPM	Eddy, County
Section	minm		0. Elevation (Show whethe	r DF, RKB, RT, GR, etc.)		
ERFORM REMEL		PLUG	NTO: AND ABANDON			REPORT OF: ALTERING CASING
ERFORM REMED EMPORARILY AB ULL OR ALTER (THER:	DIAL WORK	PLUG CHAN		REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER:		ALTERING CASING
ERFORM REMEI EMPORARILY AB ULL OR ALTER (OTHER:	DIAL WORK	PLUG CHAN	AND ABANDON	REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: and give pertinent dates, incl	X NG OPNS.	ALTERING CASING
ERFORM REMED	DIAL WORK BANDON CASING CASING Sed or Completed Operation LE 1103. MIRU slick with smalle plug. Set The would no	PLUG CHAN line uni r tool, in profi ot press t in sli	AND ABANDON	REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: and give pertinent dates, incl	X IG OPNS.	ALTERING CASING PLUG AND ABANDONMENT PLUG AND ABANDON PLUG AND ABANDON P
ERFORM REMEI EMPORARILY AN ULL OR ALTER (OTHER: 12. Describe Propo work) SEE RU 7/19/95	DIAL WORK BANDON CASING CAS	PLUG CHAN Line uni r tool, in profi ot press t in sli ressure led plug	AND ABANDON	REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: and give pertinent dates, incl ulling tool, cou profile at 11, Pumped 77 bbl nd pulled plug. 11,000'. Pum	X IG OPNS. CEMENT JOB Unding estimated date uld not reach 394'. RIH with 394'. RIH with S of KCl wat RIH with 2 p 68 bbls KC th circulatin 7'. Pump 70	ALTERING CASING PLUG AND ABANDONMENT PLUG
ERFORM REMEI EMPORARILY AN ULL OR ALTER (OTHER: 12. Describe Propo work) SEE RU 7/19/95	DIAL WORK BANDON CASING CASING Sed or Completed Operation Sed or Completed Operation Sed or Completed Operation Set or Completed Operat	PLUG CHAN Line uni r tool, in profi ot press t in sli ressure led plug	AND ABANDON	REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: and give pertinent dates, incl ulling tool, cou profile at 11, Pumped 77 bbl nd pulled plug. 11,000'. Pum sleeve. WIH wi sleeve at 10,95	X IG OPNS.	ALTERING CASING PLUG AND ABANDONMENT PLUG
ERFORM REMEI EMPORARILY AN ULL OR ALTER (THER: 12. Describe Propo work) SEE RU 7/19/95 7/20/95	DIAL WORK BANDON CASING CASING Sed or Completed Operation Set of Completed Operation Set The plug. Set The plug. Set The would not plug and set would not p RIH and pul stop and set water. The and plug.	PLUG CHAN Mions (Clearly line uni r tool, in profi ot press t in sli ressure led plug t 1 jt. went or	AND ABANDON	REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: and give pertinent dates, incl ulling tool, cou profile at 11, Pumped 77 bbl nd pulled plug. 11,000'. Pum sleeve. WIH wi sleeve at 10,95 click line unit	X IG OPNS.	ALTERING CASING PLUG AND ABANDONMENT PLUG
ERFORM REMEI EMPORARILY AR ULL OR ALTER (DTHER: 12. Describe Propo work) SEE RU 7/19/95 7/20/95	DIAL WORK BANDON CASING CASING Sed or Completed Operation Set of Completed Operation Set The plug. Set The plug. Set The would not plug and set would not p RIH and pul stop and set water. The and plug.	PLUG CHAN CHAN in chan in profi ot press t in sli ressure led plug t 1 jt. went or	AND ABANDON	REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: and give pertinent dates, incl ulling tool, cou profile at 11, Pumped 77 bbl nd pulled plug. 11,000'. Pum sleeve. WIH wi sleeve at 10,95 lick line unit	X IG OPNS.	ALTERING CASING PLUG AND ABANDONMENT PLUG AND ABANDON PLUG AN
ERFORM REMEI EMPORARILY AE ULL OR ALTER (THER:	DIAL WORK BANDON CASING CAS	PLUG CHAN chan chan chan chan chan chan chan chan	AND ABANDON	REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: and give pertinent dates, incl ulling tool, cou profile at 11, Pumped 77 bbl nd pulled plug. 11,000'. Pum sleeve. WIH wi sleeve at 10,95 click line unit	X IG OPNS.	ALTERING CASING PLUG AND ABANDONMENT PLUG

Toothman Gas Com #1, Remedial work (continued)

- 7/24/95 MIRU Service rig to find tubing leak.
- 7/25/95 Pumped 65 bbls down tubing and 35 bbls down casing to kill well. ND X-mas tree, NU BOP. POOH with 364 jts 2-7/8" tubing, Sliding sleeve and tubing seal. RIH w/ overshot to fish packer. Tested tubing in hole to 7000 psi. SDFN Found 2 holes in tubing. Appeared to be cut by Wolfcamp perfs.
- 7/26/95 Pumped 25 bbls down tubing, 35 bbls down casing to kill well. FIH with overshot, jars and tubing. Latched onto slick joint on top of packer with overshot. Jarred on packer for 4 hours, came loose. POOH with tubing and BHA. Packer showed severe corrosion. Rubbers on packer were gone. WIH with gauge ring to 11,450'. Tight spot at 11,378'. PU Baker CIBP RIH and set at 11,428' (above Morrow perforations). SDFN
- 7/27/95 Pump 50 bbls to kill well. RIH w/ tubing. 311 joints of 2-7/8" EUE 8rd, N-80, SN, tbg set at 9713. ND BOP, NU X-mas tree. RU swab, swab 89 bbls fluid. FL from surface to 4000'. SDFN. Total of 695 bbls of fluid to recover.
- 7/28/95 RU Swab, swab 146 BW. Gas increasing with each swab run.
- 7/29/95 TSIP 530 psi. CSIP 400 psi. Opened well on 20/64 choke to frac tank. Tbg dead after 2-5 minutes. RU swab FL at 4000'. Made 3 swab runs well started flowing. Swabbed / flowed 85 BW. SDFN
- 7/30/95 Swabbed / flowed 160 BW, 59 BO. SDFN
- 7/31/95 Swabbed / flowed 50 BW, 51 BO, release rig, SDFN.
- 8/1/95 FTP 480 psi, SICP 1200 psi Well flowed 31.5 BO, 20 BW, and 371 mcfg. on 30/64 choke in 24 hours. Well now only capable of producing from Wolfcamp.