**ROCA Production, Inc.** Muy Macho Com #2 (formerly the Macho Norte #1) 1980 FN & FEL of section 24, T20S, R27E API #30-015-21912 Eddy County, New Mexico

Surface casing:	13-3/8" 54.5# csg in 17½" hole @ 660' w/ 650 sx, circulated
Intermediate csg:	9-5/8" 36# K-55 csg in 121/" hole @ 2,600' w/ 1,700 sx, circulated
Production csg:	5-1/2" 17# in 8%" hole @ 11,430' w/ 525 sx, TOC @ 9,320' by temp.
_	survey
Perforations:	CIBP w/ 35' cmt @ 11,200' on perforations 11,242 – 11,250'
	open perforations 10,924 - 10,968' (Morrow)
	loc-set packer @ +/- 10,800'

- 1. Dig and line 200 bbls working pit. Flow well down as needed.
- 2. MIRU plugging equipment. NU BOP, POOH w/ production equipment.
- 3. RIH w/ tbg-set CIBP to 10,850'. Set CIBP and circulate hole w/ 240 bbls mud, pump 25 sx cement on top of CIBP @ 10,850 - 10,600'. 2010
- 4. POOH w/ tbg. 5. Stretch 5½" casing and recover based on stretch measurements, estimated 7.500'.
  - 6. RIH w/ tbg to 50' inside 51/2" stub, pump 45 sx C cmt w/ 2% CaCl2. WOC and tag this plug to insure minimum 100' plug.
  - 7. Pump 45 sx C cmt @ 4,900' (Delaware). 4700' TAG
  - 8. Pump 60 sx C cmt w/ 2% CaCl2 @ 2,650'. WOC and tag this plug no deeper than 2,550'.
  - 9. Pump 40 sx C cmt @ 710'. \* K 1 kg
  - 10. Pump 15 sx 50' to surface.
  - 11. RDMO.
  - 12. Cut off wellhead and install dry hole marker. Empty and level pit, cut off anchors, back-drag location.

StEVE MERMANN \*. Put 100' Plus @ 8700' W.C.

-,

03 Formerly the Macho Norte #1 State 016 lasse \* L6 12 and K6771

MESA MACHO COM #2



Prepared by: DENNIS KRUSE

MM#2