-		clsi
1990) DEPARTMEN	TED STATES IT OF THE INTERIOR LAND MANAGEMENT	NM OIL CONS COMMISSION Drawer 1990 APPROVED Budget Buren No. 1004-0135 Artes Expires Mar 82 108 5. Lease Designation and Serial No. MM 0354232
o not use this form for proposals to dr	AND REPORTS ON WELLS ill or to deepen or reentry to a different reserve R PERMIT—" for such proposals	6. If Induan, Allonee or Tribe Name DIT.
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
Type of Well Oil Gas Well Well Other	/	8. Well Name and No. COB547 Elizondo Atechno 1 # 2
Name of Operator OXY USA Inc.	16696	9. API Well No. 30-015-22032
Address and Telephone No. P.O. Box 50250 Location of Well (Footage, Sec., T., R., M., or Survey	Midland, TX 79710 915-685-571	10. Field and Pool, or Exploratory Area
1780 FSC 2180 FWL N	UESW (K) Sec 34 T215 R27	E 11. County or Parish, State 079730 Eddy NM
CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, RE	PORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACT	10N
Notice of Intent	Abandonment	Change of Plans
Subsequent Report	Recompletion Plugging Back Casing Repair	Non-Routine Fracturing Water Shut-Off
Final Abandonment Notice	Altering Casing Other	Conversion to Injection Dispose Water (Note: Report results of multiple completion on We Completion or Recompletion Report and Log form
give subsurface locations and measured and the ve	e all pertunent details, and give pertunent dates, including estimated date of rucal depths for all markers and zones pertunent to this work.)* O p/ug the Morrow & fes	
See	V.	SEP 25 1985
	OIL CON. DIV. DIST. 2	Carlow W
14. I hereby certary that the foregoing is true and correct Signed Car David	Stewart TideRegulatory Analyst	Date 9/22/95
(This space for Federal or State office use) Approved by	Potecioura Sectionar	Date 10/31/95
	erson knowingly and willfully to make to any department or agency of	the United States any false, fictitious or fraudulent state

San Instruction on Reverse Side

## Elizondo Federal A #5 Workover Procedures

- 1. MIRU rig. Kill well w/2%KCI. ND tree and NU BOP's. Release HES Perma Latch pkr at 11,634' and POOH w/tbg.
- RU WL. PU 5-1/2", 20# CIBP and TIH. Set CIBP at 11,350'. Test csg to 1000 psi. Dump bail 30' of cmt on top of CIBP.
- RIH w/3-1/8" select fire csg gun loaded 2 spf and perforate the Strawn in the following intervals: 10,264', 65, 66, 67, 68, 70, 71, 73, 86, 87, 88, 89, 92, 93, 94, 95, 96, 97, 98, 99, 10,300', 10,420', 21, 22, 23, 24, 25, 26, 27, 28, 70, 71, 72, 88, 89, 90'. Total of 36', 2 spf.
  - a) Depth Reference: Schlumberger Compensated Nuetron/Density log, Run #1 dated 6/9/77.
- 4. PU 5-1/2", 20# HES Perma Latch w/on/off tool and TIH. Internally test tbg to 7000 psi while TIH. Circ pkr fluid and set pkr at ± 10,160' in 5-10 pts tension.
- ND BOP's and NU tree. RU swab and swab well in. If necessary, acidize Strawn w/3000 gals of 15% NEFE HCl acid foamed to 50 quality w/CO<sub>2</sub>. Drop 110 ball sealers throughout treatment for diversion. Flow back well and allow to clean up.
   a) See BJ's stimulation recommendation.
- 6. Obtain a State 4 point test. PWOL.

2