STALE OF NEW MEXICO , ENERGY AND MINERALS DEPARTMENT	•	RECEIVED
DISTRIBUTION JANTA FE	OIL CONSERVATION DIVISION P. O. BOX 2088 RECEIVED SANTA FE, NEW MEXICO 37501	NOV 1 8 1982 Form C-103 Revised 10-1
VILE VV U.S.G.S. LAND OF FICE OPERATOR	NOV 1 2 1982	O, C. Dinatcate Type of Lease ARTESIA, DEF(Spite X) Foo S. State Oll & Gas Leave No.
	DTICES AND REPORTS ON WELL'S	DIN.
2. Name of Operator Amoco Production Company V 3. Address of Operator		8. Form or Lease Name State "EP" Com 9. Well No.
P. O. Box 68, Hobbs, New M 4. Location of Well J 198	O South 1980	10. Field and Pool, or Wildcat
	21 20-S RANGE 28-E	
	15. Elevation (Show whether DF, RT, GR, etc.) 3235.9 GR	12. County Eddy
Check Approvide Approvide Approximation Appr	opriate Box To Indicate Nature of Notice, Rep ITION TO: SU	port of Other Data BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS CHANGE PLANS CASING TEST AND CEMENT	

Propose to obtain a stabilized flow test for 5 days and perform a 144 hr. bottom hole pressure buildup test per the following:

Install additional wellhead valve (if one is not already in place) and install lubricator. Verify 1.875" profile nippl in on-off tool at ±9,166' and run in hole with tubing stops for 2-3/8" tubing and set stops in joint betweenpacker an on-off tool. Hook up test separator and prepare to flow test well. Leave well shut-in for 48 hrs. and run in with 6000 psi rated bomb. Obtain a static dip-in pressure and land bomb in tubing stop. Make gradient stops at 9000', 8000', 6000', 4000', 2000', and record surface pressure. Start flow test and obtain a stabilized flow rate to pit. Attempt to maintain a flowing tubing pressure of 200 psi. Flare well for 5 days and monitor well closely. Decrease choke size if necessary to maintain a stabilized rate. (Approval was requested and received from Les Clements 10-26-82 to flare gas from the subject well for a maximum of five days). After 5 days, run in hole with a 6000 psi rated bomb with a 144 hr. clock and land in tubing stop. Do not shut in well. Record flow rate and choke size prior to running bomb and after bomb is set. Maintain stabilized flow rate while running bomb. Run in hole with blanking plug and land in 1.875" profile nipple at ±9166'. Leave well shut in for 144 hrs. Record the pressure every 5 minutes for first hour and every 15 min. for the next 4 hr. and every 5 hrs. <u>thereafter</u>. Retrieve bomb after 144 hrs. Record the shut-in tubing pressure before and after

NIGHED A	asks m. Derring	Assist. Admin. Analyst	DATE 11-4-82
APPROVED BY	Original Signed By Leslie A. Clements	TITLE	NOV 1 9 1982
CONDITIONS OF	Supervisor District II		

retrieving plug and bomb. Rig down lubricator and evaluate.

•

,