merly 9–331)		OF LAND MANA	GEMEN	h. A.	×	<u>NM 12</u>	IAN, ALLOTTEE	OR TRIB	E NAME
SUN			ODIC (AN WELLS" CO	, 				
(Do not use this	form for proposal Use "APPLICAT	s to drill or to deep ION FOR PERMIT_	en or plug " for such p		[]: 83	7. UNIT	AGREEMENT NA	ME	
	X OTHER	Max	-1 82	har 21 8 24		8. FARM	OR LEASE NAM	(8	
NAME OF OPERATOR		MAT	- <u>1</u> -03	Child	10.53	1	ttrick Fe		n 💶
Nearburg Pro	Jucing Comp	any O.	C. D.	2.13.0		9. WBLL	#0.		
ADDRESS OF OPERATO	R	ARTES	A OFFICE				1 LD AND POOL, O	. WILDC	
P. O. Box 31	Keport location cit	arly and in accordan	ce with any	y State requirements.*					
See also space 17 be At surface	low.)					<u>Und</u> .	Morrow	BLX. AND	
2310' FSL &	960'FEL (of Sec. 11					11, T-22	L	
				ne et al etc.)		12. 000	INTT OR PARIS	H 18. m	TATE
PERMIT NO.		15. ELEVATIONS (She		DI, RI, OR, CONT		Eddy	y		NM
		4016 GI	K		eport or				
	Check Ap	propriate Box To	Indicate	Nature of Notice, R	epon, or	QUENT ESP	ORT OF:		
	NOTICE OF INTEN				B UB S		REPAIRING	WELL	
TEST WATER BHUT	-077	PULL OR ALTER CASIN	•	WATER SHUT-OL	1		ALTERING		
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREA SHOOTING OR A			ABANDONM		x-
SHOOT OR ACIDIZE		ABANDON®		(Other)	CTIVILY		iple completion	n on We	-
		CHANGE PLANS		(NOTE: I	Report_resu	indetion Re	port and Log i	(orm.)	
REPAIR WELL (Other) DESCRIBE PROPOSED		ERATIONS (Clearly sta	te all pertir ubsurface k	Completi	on or Recor	es, includin lical depthy	ag estimated d	ate of si ers and i	tarting any somes perti-
	OR COMPLETED OP If well is directi .)* M.I. and I Set HOWCO	R.U. Completi	ion Uni	Completi neut details, and give pe ocations and measured at t. Pulled tubi lug on wire lir P to 1000 PSI.	ng and ne @10, Held	Packer 334, 10 0K.	ng estimated d s for all mark C	ate of si ers and s	
(Otber) . DESCRIDE INOPOSED proposed work. nent to this work 11-28-88	OR COMPLETED OP/ If well is direction M.I. and D Set HOWCO 2% KCL wa Ran Packe Rigged up 74. 2 sh	R.U. Completi cast iron bu ter. Tested r and 2 3/8 and perfora ots per foot	ion Uni cidge p C.I.B. " Tubin ted thr . Swab	Completi neut details, and give per- coations and measured ar- t. Pulled tubin P. to 1000 PSI. ag set packer (pu tubing as for bbed welldry.	ng and ne @10, Held 10,04	Packer Packer 334, lc OK. 7'. 10,222 ed 20 1	pagestimated d for all marks baded cas 3-24, 10 bbls wate	sing w	vith
(Other) DESCRIBE PROPOSED proposed work. nent to this work 11-28-88 11-29-88	OR COMPLETED OP/ If well is direction M.I. and D Set HOWCO 2% KCL wa Ran Packe Rigged up 74. 2 sh	R.U. Completi cast iron bu ter. Tested r and 2 3/8 and perfora ots per foot SI -0 Aci mell dry.	ion Uni cidge p C.I.B. " Tubin ted thr . Swat dized w	t. Pulled tubi Plug on wire lin P. to 1000 PSI. Set packer (Tu tubing as for bbed welldry.	ng and ne @10, Held 10,04 10,04 10ws: Recover	Packer Packer 334, lc OK. 7'. 10,22 ed 20 1 rrow Fl	og eetimated d for all mark Daded cas 3-24, 10 bbls wate o Acid.	sing w	vith
(Other) DESCRIBE PROPOSED proposed work. nent to this work 11-28-88 11-29-88 11-30-88	OR COMPLETED OFFI If well is direction M.I. and D Set HOWCO 2% KCL wa Ran Packe Rigged up 74. 2 sh 14 Hrs. Swabbed w	R.U. Completi cast iron bu ter. Tested r and 2 3/8 and perfora ots per foot SI -0 Aci well dry. Re	ion Uni ridge p C.I.B. " Tubin ted thr . Swat dized w	Completi neut details, and give per- coations and measured ar- t. Pulled tubin P. to 1000 PSI. ag set packer (pu tubing as for bbed welldry.	ng and ne @10, Held 10,04 10,04 10ws: Recover	Packer Packer 334, lc OK. 7'. 10,22 ed 20 1 rrow Fl	og eetimated d for all mark Daded cas 3-24, 10 bbls wate o Acid.	sing w	vith
(Other) DESCRIBE PROPOSED proposed work. nent to this work 11-28-88 11-29-88 11-30-88 12- 1-88	OR COMPLETED OF If well is direction M.I. and D Set HOWCO 2% KCL wa Ran Packe Rigged up 74. 2 sh 14 Hrs. Swabbed v Swabbed v Swabbed v	R.U. Completi cast iron bu ter. Tested r and 2 3/8 and perfora ots per foot SI -0 Aci well dry. Re well dry in	ion Uni ridge p C.I.B. " Tubin ted thr . Swat dized w ecovered 1 hr.	Completi nent details, and give per- continues and measured ar- t. Pulled tubin P. to 1000 PSI. ag set packer (tu tubing as for- bed welldry. with 1000 gal , d 5 bbls. water	ng and ne @10, Held 10,04 10,04 10ws: Recover	Packer Packer 334, lc OK. 7'. 10,22 ed 20 1 rrow Fl	og eetimated d for all mark Daded cas 3-24, 10 bbls wate o Acid.	sing w	vith
(Otber) UEST RIBE PROPOSED proposed work. nent to this work 11-28-88 11-29-88 11-30-88 12- 1-88 12- 2-88	OR COMPLETED OF If well is direction M.I. and D Set HOWCO 2% KCL wa Ran Packe Rigged up 74. 2 sh 14 Hrs. Swabbed v Swabbed v Swabbed v	R.U. Completi cast iron bu ter. Tested r and 2 3/8 and perfora ots per foot SI -0 Aci well dry. Re	ion Uni ridge p C.I.B. " Tubin ted thr . Swat dized w ecovered 1 hr.	Completi nent details, and give per- continues and measured ar- t. Pulled tubin P. to 1000 PSI. ag set packer (tu tubing as for- bed welldry. with 1000 gal , d 5 bbls. water	ng and ne @10, Held 10,04 10,04 10ws: Recover	Packer Packer 334, lc OK. 7'. 10,22 ed 20 1 rrow Fl	og eetimated d for all mark Daded cas 3-24, 10 bbls wate o Acid.	sing w	vith
(Other) 1.1.28-88 11-28-88 11-29-88 11-29-88 11-30-88 12- 1-88 12- 2-88 12- 3-88	OR COMPLETED OF If well is direction M.I. and D Set HOWCO 2% KCL wa Ran Packe Rigged up 74. 2 sh 14 Hrs. Swabbed v Swabbed v Swabbed v	R.U. Completi cast iron bu ter. Tested r and 2 3/8 and perfora ots per foot SI -0 Aci well dry. Re well dry in	ion Uni ridge p C.I.B. " Tubin ted thr . Swat dized w ecovered 1 hr.	Completi nent details, and give per- continues and measured ar- t. Pulled tubin P. to 1000 PSI. ag set packer (tu tubing as for- bed welldry. with 1000 gal , d 5 bbls. water	ng and ne @10, Held 10,04 10,04 10ws: Recover	Packer Packer 334, lc OK. 7'. 10,22 ed 20 1 rrow Fl	og eetimated d for all mark Daded cas 3-24, 10 bbls wate o Acid.	sing w	vith
(Other) 1.1.28-88 11-28-88 11-29-88 11-29-88 11-30-88 12- 1-88 12- 2-88 12- 3-88	OR COMPLETED OF If well is direction M.I. and D Set HOWCO 2% KCL wa Ran Packe Rigged up 74. 2 sh 14 Hrs. Swabbed v Swabbed v Swabbed v	R.U. Completi cast iron bu ter. Tested r and 2 3/8 and perfora ots per foot SI -0 Aci well dry. Re well dry in	ion Uni ridge p C.I.B. " Tubin ted thr . Swat dized w ecovered 1 hr.	Completi nent details, and give per- continues and measured ar- t. Pulled tubin P. to 1000 PSI. ag set packer (tu tubing as for- bed welldry. with 1000 gal , d 5 bbls. water	ng and ne @10, Held 10,04 10,04 10ws: Recover	Packer Packer 334, lc OK. 7'. 10,22 ed 20 1 rrow Fl	og eetimated d for all mark Daded cas 3-24, 10 bbls wate o Acid.	sing w	vith
(Other) 1.1.28-88 11-28-88 11-29-88 11-29-88 11-30-88 12- 1-88 12- 2-88 12- 3-88	OR COMPLETED OF If well is direction M.I. and D Set HOWCO 2% KCL wa Ran Packe Rigged up 74. 2 sh 14 Hrs. Swabbed v Swabbed v	R.U. Completi cast iron bu ter. Tested r and 2 3/8 and perfora ots per foot SI -0 Aci well dry. Re well dry in	ion Uni ridge p C.I.B. " Tubin ted thr . Swat dized w ecovered 1 hr.	Completi nent details, and give per- continues and measured ar- t. Pulled tubin P. to 1000 PSI. ag set packer (tu tubing as for- bed welldry. with 1000 gal , d 5 bbls. water	ng and ne @10, Held 10,04 10,04 10ws: Recover	Packer Packer 334, lc OK. 7'. 10,22 ed 20 1 rrow Fl	og eetimated d for all mark Daded cas 3-24, 10 bbls wate o Acid.	sing w	vith
(Other) (Other) (Other) proposed work. nent to this work 11-28-88 11-29-88 11-30-88 12- 1-88 12- 2-88 12- 3-88 12- 4-88 12- 4-88	OR COMPLETED OFF If well is direction M.I. and I Set HOWCO 2% KCL wa Ran Packe Rigged up 74. 2 sh 14 Hrs. Swabbed v Swabbed v Swabbed v	R.U. Completi cast iron bu ter. Tested r and 2 3/8 and perfora ots per foot SI -0 Aci well dry. Re well dry in	ion Uni ridge p C.I.B. " Tubin ted thr . Swat dized w ecovered 1 hr. evalua	Completi nent details, and give per- continues and measured ar- t. Pulled tubin P. to 1000 PSI. ag set packer (tu tubing as for- bed welldry. with 1000 gal , d 5 bbls. water	ng and ne @10, Held 10, Held 10,04 110ws: Recover 7½% Mor	Packer Packer 334, lc OK. 7'. 10,22 ed 20 1 rrow Fl	page estimated d for all marks paded cas 3-24, 10 bbls wate o Acid. jas	sing w	vith -72,73,
(Other) (Other) (Other) (DENCRIBE PROPOSED proposed work. nent to this work 11-28-88 11-29-88 11-30-88 12- 1-88 12- 2-88 12- 3-88 12- 3-88 12- 4-88 12- 4-88	OR COMPLETED OFF If well is direction M.I. and I Set HOWCO 2% KCL wa Ran Packe Rigged up 74. 2 sh 14 Hrs. Swabbed v Swabbed v Swabbed v	R.U. Completi cast iron buter. Tested r and 2 3/8 and perfora ots per foot SI -0 Aci well dry. Re well dry in for further	ion Uni ridge p C.I.B. " Tubin ted thr . Swat dized w ecovered 1 hr. evalua	t. Pulled tubinent details, and give performing and measured at the pulled tubinent of the procession of the pulled tubinent of the pulled tubinent of the process of the pulled tubinent of the pulled with 1000 gal , the pulled tubinent of tu	ng and ne @10, . Held a 10,04 11ows: Recover 7½% Mor	ee, includit ical depths Packer 334, lc OK. 7'. 10,22 ed 20 f rrow F1 ce of g	page estimated d for all marks baded cas 3-24, 10 bbls wate o Acid. gas	-20-85	9 1

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

•