

|                        |   |
|------------------------|---|
| NO. OF COPIES RECEIVED |   |
| DISTRIBUTION           |   |
| SANTA FE               | ✓ |
| FILE                   | ✓ |
| U.S.G.S.               |   |
| LAND OFFICE            |   |
| OPERATOR               | ✓ |

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501  
APR 24 1985  
O. C. D.  
ARTESIA, OFFICE

Form C-103  
Revised 10-1-73

State ☒ Fee ☐

State Oil & Gas Lease No.

L-4678

SUNDRY NOTICES AND REPORTS ON WELLS  
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - II" (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL ☐ GAS WELL ☒ OTHER ☐

Name of Operator  
AMOCO PRODUCTION COMPANY ✓  
Address of Operator  
P.O. BOX 68 HOBBS, NEW MEXICO 88240

Location of well  
UNIT LETTER L 2170 FEET FROM THE South LINE AND 990 FEET FROM  
THE West LINE, SECTION 16 TOWNSHIP 22-S RANGE 26-E N.M.P.D.

Unit Agreement Name

8. Farm or Lease Name  
State "IE" Com

9. Well No.

1

10. Field and Pool, or Wildcat  
Happy Valley Morrow

15. Elevation (show whether DF, RT, GR, etc.)

3567' RDB

12. County

Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐

REMEDIAL WORK ☐  
COMMENCE DRILLING OPERATIONS ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to PXA the subject well as follows:

Notify NMOC D 24 hrs. prior to moving in service unit. MISU and load well w/ 10ppg brine. Release pkr SA 10,998 and poth w/ 2-3/8" tbg and Pkr. Run tbg and set CIBP at 10,950' (Top of Morrow perms is 11,192' and top of Morrow is 10,959'). Spot 25 SX class H neat cmt (200' plug) on top of CIBP. Spot gelled plugging mud, consisting of 10# brine w/ 25 SX gel/100 bbl. from top of cmt plug (± 10,750') to 4300'. Spot 25 SX class H neat cmt (200' plug) 9950' to 9750' which will place cmt across the top of the Penn (9918'). W/ tbg. spot 25 SX (200' plug) on top of CIBP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed Les A. Clements TITLE Administrative Analyst

DATE 26 April 1985

PROVED BY Les A. Clements TITLE Original Signed By  
CONDITIONS OF APPROVAL, IF ANY Supervisor District II

DATE JUN 04 1985

0+5 NMOC D-A, 1-JRB, 1-FSN, 1-NLG

+ 25 SX 8784' - 8584' Top w/

class A neat cmt from 7350' to 7150'. w/ tbg spot 25 SX (250') class C neat cmt. from 5150' to 4900'. This will put cmt across the top of the Bone Springs (5065'). Run freepoint. Spot plugging mud to 50' above free point. Cut csg 100' above 100% free pt. Pull and inspect csg. w/ tbg, spot 25 SX class C neat cmt from 50' below cut csg to 60' above. Then spot plugging gel to 30'. Spot 100' (34 SX) class C neat cmt. from 2950' to 2850', putting cmt across the 9 5/8" csg shoe (2900'). Spot 100' (33 SX) class C neat cmt from 733' to 633' to give plug across 13-3/8" csg shoe at 683'. w/ tbg spot 10 SX class C neat cmt from 30' to surface. Cap well and erect PXA marker. Clean location and MOSU.