SEE OTHER SIDE	PROD. ACCT.	,		6/24/93
SEE OTHER SIDE		,		
		,'		
		.'		
Change PLANS (Other) DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all proposed work. If well is directionally drilled, give subsurface nent to this work.)*	(Other) (Note: Report re <u>Completion or R</u> pertinent details, and five pertine to locations and measured and to ERFS - 11015' - 11036'	ecompletion at dates, incl	Report and Juding estimation	Log form.) ated date of starting an
NOTICE OF INTENTION TO : TESTWATER SHUT-OFF PULL OR ALTER CASING FRACTURE TREAT MULTIPLE COMPLETE	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING		"Report of: Ref Ali	PARING WELL TERING CASING ANDONMENT*
300152325400S01 Check Appropriate Box To Indicate N	3258 ature of Notices, Report		DDY er Data	NM
LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1650 FSL 1980 FEL SEC 17 NWSE 4. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12.00	OUNTY OR PAP	
		BI	10, HELD AND POOL, OR WILDCAT BURTON FLAT MORROW 11, SEC, T, R, M, OR BLK, AND SURVEY OR AREA	
DORESS OF OPERATOR P.O. BOX 50250 MIDLAND, TX 7971	0	9.WE	DVERNME	
ANE OF OPERATOR	<u>101 - 2 1993</u>	8. FAF	MORLEASE	
(Do not use this form for proposals to drill or to deepen or plug Use "APPLICATION FOR PERMIT" for such p	back to a different reservoir.		TAGREEMEN	
SUNDRY NOTICES AND REPORT				SCR385
Vember 1983) merly 9-331) DEPARTMENT OF THE INTER BUREAU OF LAND MANAGEMEN SUNDRY NOTICES AND REPORT	Γ		SE DESIGNAT	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fradulent statements or representations as to any matter within its jurisdiction.

WORKOVER PROCEDURES GOVERNMENT AG #1

- 1) MIRU rig. Kill well w/2% KCl water. ND tree and NU BOP's.
- 2) Release 5-1/2" X 2-3/8" Baker Lok-Set at 10,911' and POOH. Cull bad tbg as necessary. Send packer to shop for redress.
- 3) PU 4-5/8" RB and 5-1/2" csg scraper and TIH on 2-7/8" tbg to PBTD @ 11,055'. CHC. POOH w/bit and scraper. Run Scanalog on tbg while POOH. (ICO)
- 4) PU 2-7/8" X 5-1/2" Baker AL-2 Large Bore Lok-Set w/model FL on/off tool w/"F" profile (2.31" ID) and tailpipe described below and TIH. Set packer at ±10,830' w/10,000-12,000# compression.
 - Tailpipe: WL re-entry guide, R-nipple (Min. ID 2.197"), 2-7/8" sub.
- 5) RU swab and swab fluid level in tubing down to 5200' for 1500 psi underbalance. Maximum anticipated reservoir pressure is 4000 psi. ND BOP's and NU tree.
- 6) RU WL. Using 2-1/8" strip guns loaded 4 spf perforate the following Morrow intervals: 10,932-36' 20 shots 10,939-42' 16 shots 10,949-52' 16 shots 10,964-66' 12 shots 10,973-76' 16 shots 10,984-11,000' 68 shots 148 shots, 37 net feet Total:

Depth reference: Schlumberger DLL dated 7/12/80. Correlate depth w/Schlumberger CCL and perforating record dated 8/11/80. POOH and RD WL. RD&R rig.

- 8) Clean-up well and put on test. Report volumes and FTP until stabilized.
- 7) If necessary, RU tree saver and acidize Morrow w/7000 gals of 7-1/2% HCl plus additives as per Midland's recommendation. Acid system should be energized w/1000 scf N_2 /bbl. Drop 220 7/8" ball sealers throughout job for diversion. Swab and flow back load and put well on test.
- 8) Run 4-point test. Run BHP survey as per Midland's recommendation.