

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-34457

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal 33

9. WELL NO.

1-33

10. FIELD AND POOL, OR WILDCAT

Springs Morrow

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 33, T-20S, R-26-E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug a well in a Federal or State reserved reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Jake L. Hamon

3. ADDRESS OF OPERATOR

611 Petroleum Building, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)

At surface 1936' FSL & 690' FEL of Sec. 33

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3280' GR 3296' KB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Plug back and test Strawn

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Set CIBP at 10,000' and dumped 4 sks (35') on top of plug. 7/5/83.
2. Perforated Strawn from 9326' to 9356' with one hole per foot. 7/6/83.
3. Acidized Strawn with 3,000 gals of 10% NE FE acid by HOWCO 7/8/83.
4. Swab and swab test well. Well making 100 MCF of gas and no water.
5. Sand frac Strawn with 50,400 gals of Versagel and CO<sub>2</sub> and 47,000# of 20/40 sand by HOWCO 8/5/83.
6. Swabbed well 6 days.
7. Now testing Strawn.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Cecil H. Barton*

TITLE Production Engineer

DATE 8/22/83

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

DATE

SEP 1 1983