(Formerly 9-331)		AND MAN	AGEMENT	Verse side)	·····		se designation a 1-13232-A	
SU (Do not use t	JNDRY NOTIC his form for proposals Use "APPLICATIO	to drill or to de	epen or plug	back to a different reser	rvoir.		IDIAN, ALLOTTEE OR	
OL GAS WELL WELL	X OTHER			RECEIVED		7.UN	T AGREEMENT NAME	Ē
2. NAME OF OPERATOR	OXY USA INC.	<u>/</u>		DEC - 4 1991	1		MORLEASE NAME	AN
A LOCATION OF WELL A	P.O. BOX 50250			O. C. D.			11. NO. 1	
Soe also space 17 below. At surface		coordance with any	/ State requireme	NETRICE RATERIA	_ .		EDANDFOOL, ORW	
660 FNL 1980 FWL SEC 3 T20S R28E						S	11. SEC, T, P, M, OR BLK AND SURVEY OR AREA	
14. PETIMIT NO. 3001523562	15.1	ELEVATIONS (Show	wheter DF, RT, C	SR etc.) 3284		12.00	EC 3 T20S R2 DUNTY OR PARISH DDY	28E 13.8TATE NM
16.	Check Appropria	ate Box To I	ndicate Na	ture of Notices, R	Report,			
TESTWATER SHUT-O FRACTURE TREAT SHOOT OR ACIDIZE REPAR WELL		-		WATER SHUT-OFF FRACTURE TREATM SHOOTING OR ACT (Ofer) RECOU	aent Dizing	×	REPORT OF: REPAINING ALTERING ABANDONI	
(Other)	(Note: Report results of m				ON ts of multip	LX.J nultiple completion on Well tion Report and Log form.)		
nent to this work.)	•	onany drined, g		locations and measured	d and true	vertical de	≥pths for all marke	rs and zones
nent to this work.)	a wen is ûnecu ◆	- 4869' F		locations and measured	d and true	vertical de	≥pths for all marke	rs and zones
nent to this work.)	• SEE OTHER S	- 4869' F		locations and measured	d and true	vertical de	epths for all marke	rs and zones
TD -	• SEE OTHER S	- 4869' F	PERFS 32	locations and measured	d and true	vertical de	pths for all marke	
TD - TD - 18. Thereby certify that the k SIGNED	SEE OTHER S	- 4869' F	PERFS 32	tocations and measured	d and true	vertical de	DATE 11-15-	
18. Thoreby certify that the tasks SIGNED	SEE OTHER S	- 4869' F	PERFS 32	tocations and measured	d and true	vertical de	11.15	
18. Thoreby certify that the tasks SIGNED	11275' PBTD SEE OTHER S	- 4869' F	PERFS 32	tocations and measured	- 4422'	vertical de	DATE 11-15-	

MIRU PU, NDWH NUBOP, Rel pkr & TOOH w/ tbg. RIH w/ 5 1/2" CIBP & set @ 8920', dump 4sx (40') cmt on top, test to 1750#, held OK. Perf 4 sqz holes @ 7599' & 7600', RIH w/ ret & set @ 7580', squeeze w/ 100sx Cl H cmt + .6% Halad 9, SI WOC. RIH & tag cmt @ 7578', run temp svy, TOC @ 7250'. Perf Lower Bone Springs w/ 2 JSPF @ 7464,65,66,67,68,69,70,7471', total 16 holes. RIH w/ 2 7/8" tbg & set pkr @ 7381, swab 0-BO & 43-BW in 2 hrs, no show of oil or gas. 17hr SITP-0#, Acidize perfs 7464'-7471' w/ 4000 gal 7 1/2% NeFe HCL acid w/ 1000 SCF N2/bbl, MaxP-3880#. Swab a total of 38-BLW w/ no show of oil or gas. 14 hrSITP-100#, swab all load water, no show oil or gas.

RIH w/ 5 1/2" CIBP & set @ 7420', dump 4sx (40') cmt on top. RIH w/ jet cutter & cut 5 1/2" csg @ 6000', POOH w/ 141 jts. RIH w/ tbg to 6050' & spot 30sx Cl H cmt plug from 6050'-5950' (1/2 in & out of 5 1/2" csg sub), WOC, tag plug @ 5950'. POOH to 5200' & spot 80sx Cl H cmt plug from 5200'-5000', POOH to 2872', WOC. RIH & tag cmt @ 4998', (BLM notified, did not witness).

RIH w/ 117 jts 5 1/2" 17# csg & set @ 4943', cmt w/ 700sx Cl C cmt w/ 3% A-2 + 6#/sx salt + 1/4#/sx flocele followed by 250sx Cl C cmt w/ 5#/sx salt + .3% FL-20, circ 75sx cmt to pit (Don Early-BLM witnessed).

Perf Bone Springs w/ 2 JSPF @4286,87,88,89,90,91,92,93,94,4414,15,-16,17,18,19,20,21,4422', total 36 holes. RIH w/ 2 7/8" tbg & set pkr @ 4307'. Swab 22-BW in 5hrs, no show of oil or gas. Acidize perfs 4386'-4422' w/ 6000gal 7 1/2% NeFe HCl acid w/ 1000 SCF N2/bbl, MaxP-3050#, swab trace oil & 94-BLW in 7 hrs. 40hr SITP-500#, swab trace oil, remainder of LW & new water w/ slight show of gas.

Perf Delaware w/ 2 JSPF @ 3211,12,13,14,15,16,17,18,19,20,21,22,-23,24,25,26,27,28,29,30,84,85,86,87,88,89,90,91,92,93,94,95,96,-97,98,99,3300,1,2,3,4,5,6,7,8,9,10,11,12,13,14,15,16,17,18,19,20-21,22,23,24,25,26,27,28,29,30,31,32,33,34,35,36,37,38,39,40,41,-42,43,44,45,46,47,48,49,50', total 174 holes. RIH w/ 5 1/2 RBP & set @ 4023', test to 2000#, held OK, dump 2 sx sand on top. RIH & set pkr @ 3098, swab 16-BW in 10hrs w/ no show of oil or gas. Acidized perfs <math>3211'-3350' w/ 4000 gal 7 1/2% NeFe HCl acid, MaxP-1320#. Swab 30-BLW in 8 hrs w/ no show of oil or gas. 43hr SITP-0#, Frac perfs 3211'-3350' w/ 16000gal gelled 2% KCl w/ 16000 gal CO2 w/ 68500# 12/20 sand, MaxP 3070#. SI-3hrs, open well to test tank, flwd 264-BLW in 18 hrs w/ FTP-400#, no show of oil & good show of gas. Swab trace oil, remainder of LW & new water w/ good show of gas. CHC, POOH w/ RBP, RIH w/ 27/8" tbg to 3098', NDBOP, NUWH. RDPU, well is temporarily abandoned pending geological & engineering evaluation, 5/3/91.