

Form 3160-5  
(November 1983)  
(Formerly 9-331)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLI  
(Other instructions  
verse side)

TE  
re

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

91-016916 NM-08277

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL ☐ GAS WELL ☒ OTHER

Injection Well

NOV 27 '89

2. NAME OF OPERATOR

Barber Oil, Inc. ✓

O. C. D.

3. ADDRESS OF OPERATOR

P. O. Box 1658 Carlsbad, NM 88221-1658

ARTESIA, OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)  
At surface

Unit Letter (N)

1315' FSL and 1325' FWL

7. UNIT AGREEMENT NAME

Saladar Unit

8. FARM OR LEASE NAME

9. WELL NO.

14

10. FIELD AND POOL, OR WILDCAT

Saladar - Yates

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 33, T20S, R28E

12. COUNTY OR PARISH

EDDY

13. STATE

NM

15. ELEVATIONS (Show whether OF, RT, GR, etc.)

3197 GR

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRAC TREAT

MULTIPLE COMPLETION

SHOOT & ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRAC TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

16. WORK PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Workover - Unseat packer, tag bottom and tally tubing to check PBTD. Calculate amount of blow sand need to cover perforations from 626' to 638' and dump sand in casing. Allow to settle for two days. Run wire line to check PBTD. Adjust sand level as needed. Go in hole with packer and tubing and set at 600'. Cement squeeze perforations from 613' to 626'. Shut down overnight. Come out of hole with tubing and packer. Go in hole with bit and tubing, drill out cement and clean out blow sand to plug back total depth of 648'. Come out of hole with tubing and bit. Go in hole with packer and tubing and set at 600'. Acidize perforations from 626' to 638' with 500 gals of acid by displacing acid to the perms. Do not overflush. Wait one hour and swab acid load back until well cleans up. Pump another 250 gals. acid and overflush acid into formation. Return well to injection.

RECEIVED

NOV 16 3 07 PM '89

I hereby certify that the foregoing is true and correct.

SIGNED

TITLE President

DATE 11/15/89

This space for Federal or State police use

APPROVED BY

TITLE

DATE 11/26/89

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.