

Doris Federal #1
Burton Flat Field

Recompletion Procedure

- (1) Move in and rig up W.O. rig. Load well with 10 #/G brine.
- (2) Release Baker Model "R" packer set at 10855' with 10000# compression. POH with tubing.
- (3) Rig up W.L. unit. Run gauge ring & junk basket to 10950'. Set bridge plug at 10900' and cap with 35' of cement.
- (4) Set bridge plug at 9250' and cap with 35' of cement.
- (5) Perforate 4521'-4546', with 4 HPF.
- (6) Run 5-1/2" Model "R" packet & set at 4400'±.
- (7) Stimulate Delaware perforations with acid and/or frac job as per attached recommendation.