

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, NM 87505

WELL API NO.
30-015-24959

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

Burton Flat

8. Well No.

2

9. Pool name or Wildcat

NW Fenton

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Merit Energy Company

3. Address of Operator

12222 Merit Drive Suite 1500 Dallas, Texas 75251

4. Well Location

Unit Letter 0 : 3300 feet from the South line and 1980 feet from the East line

Section 1 Township 21S Range 27E NMPM County Eddy

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3178' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

- 1) Dig, fence & line 150 bbl. working pit.
 - 2) Unseat pump & LD rods. NU tbg. BOP.
 - 3) Circulate hole w/mud (25# salt gel/bbl. brine).
 - 4) POOH standing back production tbg.
 - 5) RIH w/CIBP for 5-1/2" csg. on WL & set & 2850'. Dump bail 35' cmt on top of CIBP.
 - 6) ND wellhead & stretch 5-1/2" csg. Cut & pull csg. from freepoint. Use BOP on csg.
 - 7) RIH w/tbg. to 2589'. Pump 60 sx. "C" cmt. w/2% CaCl2. WOC & tag plug @ least 50' above csg. stub & 8-5/8" shoe.
 - 8) Pressure test 8-5/8" csg. to 500 psi.
 - 9) RIH w/tbg. to 680'. Pump 35 sx. "C".
 - 10) ND BOP & pump 10 sx. "C" cmt. 30' to surface. RDMO.
 - 11) Cut off wellhead & anchors. Install dryhole marker. Empty work pit. Cover work pit, cellar & anchors. Leave location clean.
- Well bore schematic attached.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Lynne Moon TITLE Regulatory Analyst DATE 11/17/99

Type or print name Lynne Moon Telephone No. 972-383-6569
(This space for State use)

APPROVED BY mae steel TITLE Field Rep. II DATE 11/23/99
Conditions of approval, if any:

* Notify NMOC to witness plugging operations.