

## ATTACHMENT I

### Recompletion Procedure Item 13

11. Released RTTS pkr & POOH w/pkr, mech. collar locator, SN and 2 7/8" tbg.
12. RIH W/1 jt 2 7/8" tbg, 5 1/2" Lok-Set pkr, Baker "F" nipple on 2 7/8" tbg.
13. ND BOP's. NU wellhead. Pump pkr fluid down backside. Set pkr @ 7210'. Tested backside to 600 psig.
14. RU swab. Swab well in. Start flowing well to test.
15. Kill well w/2% KCL wt. ND wellhead. NU BOP's.
16. Release Lok-Set pkr and POOH w/pkr, "F" nipple and 2 7/8" tbg.
17. RU Wireline. RIH w/5 1/2" cmt retainer and CCL. Ran CCL correlation strip & set cmt retainer @ 7400' KB. RD wireline.
18. RIH w/1 jt tbg. w/WL re-entry guide, 5 1/2" Lok-Set pkr, and Model "F" nipple.
19. ND BOP's. Pumped pkr fluid down backside. Set pkr @ 7205'. NU wellhead. Press. backside to 500 psig.
20. RU swab. Swab well in. Start flowing well to test.
21. RDMO pulling unit.