

(November 1983)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions
verse side)

Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-76919

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Roaring Spring Fed. Com.

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Indian Basin Morrow

11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREA

Sec. 14, T-21-S, R-23-E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Bill Fenn, Inc.

3. ADDRESS OF OPERATOR

P. O. Drawer 569, Giddings, Texas 78942

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1650' FNL & 990' FWL

RECEIVED

FEB -7 '90

O. C. D.
ARTESIA, OFFICE

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3791.6 GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Intent to Plug & Abandon

X

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

PLEASE SEE DETAILED PROCEDURE ON REVERSE SIDE

CORRECTED COPY

* NOTIFY BLM PRIOR TO COMMENCING P&A.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Agent

DATE 1/11/90

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the
United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

RECEIVED

JAN 10 9 25 AM '90

Procedure

1. Move-in and rig-up pulling unit and other equipment as required.
2. Blow down both strings of tubing and casing; load both strings and annulus with water.
3. Remove dual tree and install 7-1/16" by 3000 psig BOP with off-set rams.
4. Pull short string stringer from top packer and trip out of hole; lay down tubing and equipment.
5. Unseat top packer, unseat bottom packer and trip out of hole with upper string; lay down equipment. Keep hole loaded with water.
6. Go in hole with tubing and set plugs as follows:
Run and set a CIBP at 8,300' KB; dump 50 feet of cement on top (tag not required).
Run and set a CIBP at 7,400' KB; dump 50 feet of cement on top (tag not required).
Run free point; cut and pull 7" casing from approx. 6100' KB.
7. Go in hole with tubing; set a 200' cement plug from 100 feet into stub to 100 feet above.
Note: If casing is cut and pulled above 6000' KB, BLM requires a 100 foot plug in casing from 6100' up to 6000' KB (tag not required).
8. Pull out of hole with tubing (lay down as pulled); set a 100' cement plug from 3152' to 3052' KB; tag not required unless hole taking fluid, if so, then wait and tag plug to confirm setting depth.
9. Pull out of hole with tubing (lay down as pulled); set a 100' cement plug from 2048' to 1948' KB; tag not required unless hole taking fluid, if so, then wait and tag plug to confirm setting depth.
10. Pull out of hole with tubing (lay down as pulled); set a 100' cement plug from 355' to 255' KB (tag not required).
11. Spot a 50 foot plug from surface down.
12. Cut off casing approx. four feet below ground level; weld a 3/4" plate on top and install dry hole marker.
13. Clear and level location; rip road and location and reseed as required by BLM.

Note: Displace hole with 10#/gal. mud between plugs