

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

NM OIL CONS COMMISSION

Drawer DD

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT - " for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Santa Fe Energy Resources, Inc.

3. Address and Telephone No.

550 W. Texas, Suite 1330, Midland, TX 79701 915/687-3351

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

(C), 1294' FNL, & 2063' FWL, Sec. 5, T-22S, R-24E

5. Lease Designation and Serial No.

NM-81217

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Bandaid Federal #1

9. API Well No.

Unknown 30-015-26144

10. Field and Pool, or exploratory Area

Indian Basin (Upper Penn) Assoc.

11. County or Parish, State

Eddy NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other  
☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water\*

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

It is planned to plug and abandon the subject well as follows:

1. If necessary kill well with 9 ppg mud. MIRU PU and NU BOP.
2. Release packer and POH with tubing.
3. RIH w/ gauge ring and set EZSV retainer at +7100'. RIH w/ tubing and sting into retainer.
4. Mix and pump 150 sx C1 "C" cement. Sting out of retainer and pump 50' cement plug on top of retainer. POH and WOC. Tag plug.
5. Load hole with 9 ppg mud. POH laying down tubing.
6. Install wellhead w/ 3 to 5 joints tubing for kill string and valve.
7. Pump 150 sx C1 C cmt plug to a minimum 75' above 7" csg stub. WOC and tag plug.
8. Set a 100' cmt plug in open hole midway between 9-5/8" casing shoe and 7" csg stub. WOC and tag plug.
9. Set 150' cmt plug across 9-5/8" csg shoe (2575'-2425'). WOC & tag plug.
10. Set 100' cmt plug across 13-3/8" csg shoe (394'-294'). Set 50' surface plug.
11. Erect P&A marker, clean and restore location.

This procedure was coordinated with Joe Lara of BLM by telephone on 11/9/94.

14. I hereby certify that the foregoing is true and correct

Signed Serry McLaughlin Sr. Production Clerk

Date July 25, 1995

(This space for Federal or State office use)

Approved by (ORIG. SCD.) JOE G. LARA

Title

PETROLEUM ENGINEER

Conditions of approval, if any: See attached

Date 7/27/95