Submit 3 Copies to Appropriate District Office	State of New Mexico rgy, Minerals and Natural Resources Departm.	Form C-103
DISTRICT I P O. Box 1980, Hobbs, NM 88240 DISTRICT II P O Drawer DD, Artesia, NM 88210 DISTRICT III DISTRICT DISTRI	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088	WELL API NO. 30-015.62832 5. Indicate Type of Lease STATE State Oil & Gas Lease No. L-7010
(DO NOT USE THIS FORM FOR PRO DIFFERENT RESERV (FORM C-	CES AND REPORTS ON WELLS POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A /OIR. USE "APPLICATION FOR PERMIT" 101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name OXY STATE
Type of Well Gas Weil Other Veil Veil Other		8. Well No.
3. Address of Operator 20 NORTH BROADWAY, SUITE 15	00, OKLAHOMA CITY, OKLAHOMA 73102 (405) 235-3611	2 9. Pool name or Wildcat Catclaw Draw, East (Delaware)
+ Well Location Unit Letter <u>M</u> : <u>330</u> Feet From Th	e <u>SOUTH</u> Line and <u>990</u> F	eet From The <u>WEST</u> Line
Section 9 Township 21	S Range 26E NMPM 10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 3242'	1 EDDY County
Check Appro	priate Box To Indicate Nature Of Notice, Report, Or	Other Data
NOTICE OF INTER	ITION TO: SUBSEQ	UENT REPORT OF:
	LUG AND ABANDON I REMEDIAL WORK CHANGE PLANS I COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JO	ALTERING CASING Image: Constraint of the second s
OTHER:	tate all pertinent details, and give pertinent dates, including estimated date of stark	Π

Devon Energy Corporation (Nevada) plans to T&A this wellbore by filling the wellbore with inhibited fluids, placing a CIBP over the perforations which are currently open, and performing a Mechanical Integrity Test on the casing. This field exhibits formation characteristics which seem to make it a suitable secondary recovery candidate. Devon Energy Corporation (Nevada) wishes to preserve this wellbore for further utilization should the field be placed on secondary recovery. Attached please find the following.

4

OCD PECEVEED PRICES

- 1. Procedure to temporarily abandon wellbore
- 2. Current wellbore schematic (well is SI)
- 3. Proposed schematic of T&A'd wellbore

Chis space for State USESSING STREET BY THE W. GUM DECARD OF SUPERVISOR Approved by TITLE	JAN 1 3 1998
TYPE OR PRINT NAME Candace R. Graham	TELEPHONE NO. (405) 235-3611
SIGNATURE Candace R. Draham TITLE ENGINEERING TECHNICI	AN DATE January 13, 1998

DEVON ENERGY CORPORATION Interoffice Correspondence

1/12/98 10:10 AM

TO: Rick Clark

FROM: W. M. Frank

- RE: Procedure to Temporarily Abandon Well Oxy State #2 330' FSL & 900' FWL Section 9-T21S-R26E Eddy County, New Mexico
- Well Data: Elevation 3242' GL 3251' KB.

TD - 4265' Driller

Casing - 13-3/8" 48# @ 330' Cemented to Surf - 8-5/8" 24# @ 2160', 1" to Surface - 5-1/2" 17# @ 4265' Cmt w/450 sx

Note: Location will have H2S present. All personnel on location must have H2S certification. Conduct H2S safety meetings at each stage of procedure involving gas reaching surface. <u>Make sure that all personnel are aware of safety procedures</u>.

Procedure

- 1. MIRU DDPU. Lay down tubing (believe that there is only one joint of tubing in hole).
- 2. MIRU electric line truck. TIH w/gage ring and tag CIBP @ ±3000'. Dump bail 35' of "C" cement on top of CIBP.
- MIRU pump truck. Bull head 55 bbls inhibited 2% KCl water down casing. Do not go over 1000 psig injection pressure.
- 4. PU setting tool and CIBP. TIH w/CIBP slowly. Set CIBP @ 2,150'. Correleate depth to CBL of 10/16/91. RDMO electric line truck and DDPU.
- 5. Make up dry hole flange. Test CIBP and casing to 500 psig f/30 min on chart w/OCD witnessing. RDMO pump truck.



Oxy2.SCH



