- Submit 3 Copies to Appropriate	Energ	State of New Mexico Energy, Minerals and Natural Resources Department		Form C-103 Revised 1-1-89
District Office	ОП	OIL CONSERVATION DIVISION		WELL API NO.
P.O. Box 1980, Hobbs, NM 8	38240	P.O. Box 2088 Santa Fe, New Mexico 87504-2088		30-015-26916
<u>DISTRICT II</u> P.O. Drawer DD, Artesia, NM	88210			5. Indicate Type of Lease STATE FEE X
<u>DISTRICT III</u> 1000 Rio Brazos Rd., Aztec, N	JUN 1 Aziec, NM 87410		JUN 1 0 1992	6. State Oil & Gas Lease No.
		O. C. D.		
SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN O DIFFERENT RESERVOR. USE "APPLICATION FOR PERI (FORM C-101) FOR SUCH PROPOSALS.)			R PERMIT	7. Lease Name or Unit Agreement Name
I. Type of Well:	GAS WELL X	OTHER		Mojave AJY Com
2. Name of Operator				8. Well No.
YATES PETROLEUM CORPORATION				9. Pool name or Wildcat
3. Address of Operator 105 South 4th St., Artesia, NM 88210				South Dagger Draw U/Penn
4. Well Location		,	· · · · · · · · · · · · · · · · · · ·	boden bagger blaw offenn
Unit Letter <u>X</u> Z	<u>C</u> : <u>990</u> F	et From The North	Line and660	Feet From TheEast Line
5 arise 35	T	ownship $20\frac{1}{2}$ -S	Range 23-E	NMPM Eddy County
Section Section	mmm	10. Elevation (Show wh	hether DF, RKB, RT, GR, etc.)	
		3700'	GR	
11.	Check Appro	opriate Box to Indic	ate Nature of Notice, F	Report, or Other Data
NOTICE	E OF INTENT	FION TO:	SUE	BSEQUENT REPORT OF:
PERFORM REMEDIAL WOR	як 🗌 👘	PLUG AND ABANDON		ALTERING CASING
		PLUG AND ABANDON CHANGE PLANS		
EMPORARILY ABANDON				
			COMMENCE DRILLIN	
TEMPORARILY ABANDON PULL OR ALTER CASING DTHER:		CHANGE PLANS	CASING TEST AND C	IG OPNS. PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Con- work) SEE RULE 1103. 5-21-92. Tested 8896-8900' w/10 N2/bb1. Swabbed, Perforated 8551-4 8551-53' w/500g. 8461-66' w/1000g 5-29-92. Bled we and spot 250g. 20 three days. Rele 20% NEFE @ 7512' (2 SPF). Swab we retainer @ 7450' to 4000 psi w/61 retainer @ 7450'	mpleted Operations (Morrow - re .42" holes-2 recovered 2 43' w/6 .42 7½% MSA w/2 .7½% MSA w/2 .7½% MSA w/2 ell down. Per ease packer . TOH w/tub rell, recover . Cmt'd w/2 sx in form . Test squ	CHANGE PLANS Clearly state all perinent det ecovered 83 BW. 2 SPF. Acidized 2 bbls gas cut f " holes-2 SPF. a 1000 SCF N2/bbl. /1000 SCF N2/bbl. /1000 SCF N2/bbl. Acidized 2 bbls gas cut f " holes-2 SPF. a 1000 SCF N2/bbl. /1000	COMMENCE DRILLIN CASING TEST AND C OTHER: SET CIBI ails, and give pertinent dates, incl set 7" CIBP @ 90! a perfs 8896-8900' fluid. Bled off. and 8461-66' w/12 Flowed well to p c. Recovered total COH. Set CIBP @ 84 2'.42" holes (2 Si w/RBP, set @ 7600' asing to 1000 psi. 1 ittle gas. Relea 10% CF-14 and 100 at of retainer. TI 500 psi. TOH. Spo Age and belief.	AG OPNS. PLUG AND ABANDONMENT P. PERFORATE & TREAT X Muding estimated date of starting any proposed 50' w/35' cement cap. Perforated w/1000g. 7½% MSA acid w/1000 SCF Set CIBP @ 8875' w/35' cement cap. .42" holes-2 SPF. Acidized perfs pit - died in 1½ hrs. Acidized perfs 15 bbls. 425' w/35' cement cap. TIH to 7680 PF). Produced thru separator for , tested to 1500 psi. Spot 250g. Perforated 7500-7504' w/8 .42" hol ased packer. Set 7" SVEZ drill sx "H" Neat. Squeeze perfs 7500-750 H w/bit and drill collars, drilled t 250g. 20% NEFE @ 7450'. (cont'd page 2)
TEMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Con- work) SEE RULE 1103. 5-21-92. Tested 8896-8900' w/10 N2/bb1. Swabbed, Perforated 8551-4 8551-53' w/500g. 8461-66' w/1000g 5-29-92. Bled we and spot 250g. 20 three days. Rele 20% NEFE @ 7512' (2 SPF). Swab we retainer @ 7450' to 4000 psi w/61 retainer @ 7450'	mpleted Operations (Morrow - re .42" holes-2 recovered 2 43' w/6 .42 7½% MSA w/2 .7½% MSA w/2 .7%% MSA w/2	CHANGE PLANS Clearly state all periment det ecovered 83 BW. 2 SPF. Acidized 2 bbls gas cut f " holes-2 SPF. a 1000 SCF N2/bbl. /1000 SCF N2/bbl. /1000 SCF N2/bbl. Release tools. T rforated 7670-72 and TOH. TIH w ing. Pressure ca red 88 BW, very 100 sx "H" w/5/1 ation. Stung ou eeze holes to 15 supplete to the best of my knowless <i>O o MIM</i>	COMMENCE DRILLIN CASING TEST AND C OTHER: SET CIBI ails, and give pertinent dates, incl set 7" CIBP @ 90! a perfs 8896-8900' fluid. Bled off. and 8461-66' w/12 Flowed well to p c. Recovered total COH. Set CIBP @ 84 2'.42" holes (2 Si w/RBP, set @ 7600' asing to 1000 psi. 1 ittle gas. Relea 10% CF-14 and 100 at of retainer. TI 500 psi. TOH. Spo Age and belief.	AG OPNS. PLUG AND ABANDONMENT P. PERFORATE & TREAT X P. PERFORATE & TREAT X Auding estimated date of starting any proposed 50' w/35' cement cap. Perforated w/1000g. 7½% MSA acid w/1000 SCF Set CIBP @ 8875' w/35' cement cap. .42" holes-2 SPF. Acidized perfs pit - died in 1½ hrs. Acidized perfs 15 bbls. 425' w/35' cement cap. TIH to 7680 PF). Produced thru separator for , tested to 1500 psi. Spot 250g. Perforated 7500-7504' w/8 .42" hol ased packer. Set 7" SVEZ drill sx "H" Neat. Squeeze perfs 7500-750 H w/bit and drill collars, drilled t 250g. 20% NEFE @ 7450'. (cont'd page 2) Supervisor DATE 6-8-92
TEMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Con- work) SEE RULE 1103. 5-21-92. Tested 8896-8900' w/10 N2/bb1. Swabbed, Perforated 85514 8551-53' w/500g. 8461-66' w/1000g 5-29-92. Bled we and spot 250g. 20 three days. Rele 20% NEFE @ 7512' (2 SPF). Swab we retainer @ 7450' to 4000 psi w/61 retainer @ 7450' I bereby certify that the information (2 A A A A A A A A A A A A A A A A A A A	mpleted Operations (Morrow - re .42" holes-2 recovered 2 43' w/6 .42 7½% MSA w/2 .7½% MSA w/2 .7½% MSA w/2 ell down. Per ease packer . TOH w/tub rell, recover . Cmt'd w/2 sx in form . Test squ	CHANGE PLANS Clearly state all periment det ecovered 83 BW. 2 SPF. Acidized 2 bbls gas cut f " holes-2 SPF. a 1000 SCF N2/bbl. /1000 SCF N2/bbl. /1000 SCF N2/bbl. Release tools. T rforated 7670-72 and TOH. TIH w ing. Pressure ca red 88 BW, very 100 sx "H" w/5/1 ation. Stung ou eeze holes to 15 supplete to the best of my knowless <i>O o MIM</i>	COMMENCE DRILLIN CASING TEST AND C OTHER: SET CIBI ails, and give pertinent dates, incl set 7" CIBP @ 90! a perfs 8896-8900' fluid. Bled off. and 8461-66' w/12 Flowed well to p c. Recovered total COH. Set CIBP @ 84 2'.42" holes (2 Si w/RBP, set @ 7600' asing to 1000 psi. 1 ittle gas. Relea 10% CF-14 and 100 at of retainer. TI 500 psi. TOH. Spo Age and belief.	AG OPNS. PLUG AND ABANDONMENT P. PERFORATE & TREAT X Muding estimated date of starting any proposed 50' w/35' cement cap. Perforated w/1000g. 7½% MSA acid w/1000 SCF Set CIBP @ 8875' w/35' cement cap. .42" holes-2 SPF. Acidized perfs pit - died in 1½ hrs. Acidized perfs 15 bbls. 425' w/35' cement cap. TIH to 7680 PF). Produced thru separator for , tested to 1500 psi. Spot 250g. Perforated 7500-7504' w/8 .42" hol ased packer. Set 7" SVEZ drill sx "H" Neat. Squeeze perfs 7500-750 H w/bit and drill collars, drilled t 250g. 20% NEFE @ 7450'. (cont'd page 2)
TEMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12 Describe Proposed or Con- work) SEE RULE 1103. 5-21-92. Tested 8896-8900' w/10 N2/bb1. Swabbed, Perforated 8551 8551-53' w/500g. 8461-66' w/1000g 5-29-92. Bled wo and spot 250g. 20 three days. Refe 20% NEFE @ 7512' (2 SPF). Swab wo retainer @ 7450' to 4000 psi w/61 retainer @ 7450' I hereby cartify that the information SIONATURE	mpleted Operations (Morrow - re .42" holes- recovered 2 43' w/6 .42 7½% MSA w/ .7½% MSA w/ ell down. Per ease packer . TOH w/tub ell, recover . Cmt'd w/ sx in form . Test squ Juanita Go ORIGINAL S MIKE WILL	CHANGE PLANS Clearly state all periment det ecovered 83 BW. 2 SPF. Acidized 2 bbls gas cut f " holes-2 SPF. a 1000 SCF N2/bbl. /1000 SCF N2/bbl. /1000 SCF N2/bbl. Release tools. T rforated 7670-72 and TOH. TIH w ing. Pressure ca red 88 BW, very 100 sx "H" w/5/1 ation. Stung ou eeze holes to 15 spilate to the best of my knowle 0 o diata	COMMENCE DRILLIN CASING TEST AND C OTHER: SET CIBI ails, and give pertinent dates, incl set 7" CIBP @ 90! a perfs 8896-8900' fluid. Bled off. and 8461-66' w/12 Flowed well to p c. Recovered total COH. Set CIBP @ 84 2'.42" holes (2 Si w/RBP, set @ 7600' asing to 1000 psi. 1 ittle gas. Relea 10% CF-14 and 100 at of retainer. TI 500 psi. TOH. Spo Age and belief.	AG OPNS. PLUG AND ABANDONMENT P. PERFORATE & TREAT P. PERFORATE & TREAT Auding estimated date of starting any proposed 50' w/35' cement cap. Perforated w/1000g. 7½% MSA acid w/1000 SCF Set CIBP @ 8875' w/35' cement cap. .42" holes-2 SPF. Acidized perfs pit - died in 1½ hrs. Acidized perfs 15 bbls. 425' w/35' cement cap. TIH to 7680 PF). Produced thru separator for , tested to 1500 psi. Spot 250g. Perforated 7500-7504' w/8 .42" hol ased packer. Set 7" SVEZ drill sx "H" Neat. Squeeze perfs 7500-750 H w/bit and drill collars, drilled t 250g. 20% NEFE @ 7450'. (cont'd page 2) Supervisor DATE 6-8-92

: