Form 3160-5 (June 19^0)		ED STATES	N.M	- Sivision
(June 19 0)		ND MANAGEMENT	311 S 151 3 Arte ol. NM	10-2834 sget Bureau No. 1004-0135 Expires March 31, 1993
	••••••••••	ND REPORTS ON WELLS		5. Lease Designation and Serial No.
Do not use this form	for proposals to drill or t	to deepen or reentry to a diff	erent reservoir.	NM-NM84
L	se "APPLICATION FOR	PERMIT-" for such propos	sals	6. If Indian, Allottee or Tribe Name
	SUBMIT IN	N/A 7. If Unit or CA, Agreement Designation		
1. Type of Well	Other			N/A
2. Name of Operator				8. Well Name and No.
	GY CORPORATION (NEVAD	A)		INEXCO "17" FEDERAL #2
3. Address and Telephone	No.	9. API Well No.		
20 NORTH BR	OADWAY, SUITE 1500, OKL	AHOMA CITY, OKLAHOMA 7310	2 (405) 235-3611	30-015-27804
1 Location of Well (Foota	ge. Sec., T., R., M., or Survey De	scription)	UN RECEIVED RECEIVED OCD ARTESIA	- 10. Field and Pool, or Exploratory Area
•	1800' FEL, Unit J, Sec	17-T21S-R26E	OFUCINESIA	Catclaw Draw (Morrow)
	1514' FEL, Unit B, Sec	17-T21S-R26E	OCD - AKIL	11. County or Parish, State
		· · · · · · · · · · · · · · · · · · ·		Eddy Cnty, NM
CHECK AP	PROPRIATE BOX(s)	TO INDICATE NATURE (	OF NOTICE, REP	ORT, OR OTHER DATA
TYPE OF SU	BMISSION		TYPE OF ACTION	
Notice of Intent		Abandonment		Change of Plans
		Recompletion		New Construction
Subsequent Report		Plugging Back		Non-Routine Fracturing
_		Casing Repair		Water Shut-Off
Final Abandonment N	otice	Altering Casing		Conversion to Injection
			nulate Upper Morrow	[] Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
13. Describe Proposed or Com subsurface locations and	pleted Operations (Clearly state all per d measured and true vertical depths for	tinent details, and give pertinent dates, inclu all markers and zones pertinent to this work	ding estimated date of starting )*	any proposed work. If well is directionally drilled, give

Within the next two weeks, we plan to set and cement a CIBP at 10,950' then proceed with workover to perforate the Upper Morrow and stimulate same. Attached please find the following.

••

- 1. Engineer's workover procedure
- 2. Current well bore schematic (well is TA'd)
- 3. Rodstar down hole pump analysis
- 4. Copies of log sections
- 5. BLM letter -- SW-907 3105.2 (06200)

14. I hereby certify	that the foregoing is true and correct		
^		Candace R. Graham	
Signed Can	dace R. Graham	Title Engineering Technician	Date <u>May 19, 1998</u>
(This space for Fed	eral or State office use)		NNN 4 0 4000
Approved by	(ORIG. SGD.) DAVID R. GLASS	Tit PETROLEUM ENGINEER	<b>JUN 1 9 1998</b>

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representatio to any matter within its jurisdiction.

## DEVON ENERGY CORPORATION Interoffice Correspondence

Monday, May 18, 1998

- TO: Rick Clark
- FROM: W.M. Frank
- RE: Recompletion Prognosis Inexco 17-2 (DEC - 97%) 2300' FSL & 1800' FEL (Surface) 776' FNL & 1517' FEL (TD) Section 17-T21S-R26E Eddy County, New Mexico
- Well Data: Elevation 3299' R.K.B. 3280' GL

TD - 11,370' MD PBTD - 11,300' MD

Perforations - 11,040-11,240' Morrow (OA)

Casing - 13-3/8" 48# J-55 @ 491' Cmt to Surface

- 8-5/8" 24# K-55 @ 2113' Cmt to Surface
  - 4-1/2" 11.6 & 13.5#, N-80 @ 11,370' w/790 sx TOC -8097' (Temp Survey). Casing perf'd at 3,530' and 910 sxs cement circulated in annulus, no cement to surface.

Packer – Arrow set permanent packer @ 10,911' 2 3/8", 4.7#, N-80, 8rd AB Modified Tubing

Capacity - 0.0039 Bpf Displacement - 0.00171 Bpf Burst - 11200 psig new, 8400 psig @ 75%

## **Procedure**

## NOTE: ALL DEPTHS ARE MEASURED DEPTH UNLESS OTHERWISE SPECIFIED.

1. MIRU DDPU. Blow down well until well dies. If necessary, kill well with 2% KCl containing 1 gpt clay stabilizer. Use as little kill fluid as possible.

2. ND wellhead. NU BOPE.

- 3. Release seal assembly from packer (should take just straight pull) and POOH standing back tubing.
- 4. MIRU electric line company w/pack-off lubricator. TIH w/CIBP and set @ 10950'. Dump bail a minimum of 35' of cement on top of CIBP. Correlate depth with Long Spaced Sonic Log of 3/30/94. RDMO electric line company.
- 5. TIH w/Baker MAX packer and L-10 On/Off Tool on 2 3/8" tubing to 10,360'. Hydrotest 2 3/8" to 8,000 psig.
- 6. Before setting packer, "pickle tubing" with 750 gals 15% HCl. Pump acid down tubing at 1 bpm to the EOT and then reverse acid out at 1 bpm with produced water.
- 7. Set packer @ 10,360'. Load annulus w/inhibited 2% KCl substitute packer fluid. Test annulus to 1,000 psig f/15 minutes.
- 8. ND BOP. NU tree. Swab fluid level in tubing down to 9,000' from surface. This will provide 1,400' of fluid cover above the perf guns.
- 9. MIRU electric line unit w/full 3000 psi lubricator. Perforate the Upper Morrow lime formation under-balanced at the following depths:

10,532 - 33' (Limestone)	2 jspf	3 shots
10,535 - 36' (Limestone)	2 jspf	3 shots
10,537 - 38' (Limestone)	2 jspf	3 shots
10,567 - 68' (Limestone)	2 jspf	3 shots
10,572 - 74' (Limestone)	2 jspf	5 shots
10,577 - 78' (Limestone)	2 jspf	3 shots

A total of 20 shots. Correlate depth with Long Spaced Sonic Log of 3/30/94. RDMO electric line unit.

- 10. Turn well to sales and flow test well.
- 11. If well does not flow, swab test well and record fluid entry per hour.
- 12. MIRU BJ Services. Acidize Morrow intervals as per service company recommendation.
- 13. Swab back load and flow test well. If well is commercial, put well to sales.
- 14. If Morrow proves non-commercial then kill well with FSW. Release packer and POOH standing back tubing.

- 15. MIRU electric line company w/pack-off lubricator. TIH w/CIBP and set @ 10,430'. Dump bail a minimum of 35' of cement on top of CIBP. Correlate depth with Long Spaced Sonic Log of 3/30/94. RDMO electric line company.
- 16. TIH with a 2 3/8" SN on tubing to 10,300'. Circulate hole with 160 bbls of plug mud.
- 17. POOH w/tubing to 10,154'. Spot a 25 sx Class "H" cement in a balance plug to the EOT. Slowly POOH laying down 10 joints of tubing. Reverse circulate the tubing clean. Continue POOH to 9,588'. Spot a 25 sx Class "H" cement in a balance plug to the EOT. Slowly POOH laying down 10 joints of tubing. Reverse circulate the tubing clean. POOH w/tubing to 7,704'. Spot a 25 sx Class "H" cement in a balance plug to the EOT. Slowly POOH laying down 10 joints of tubing. Reverse circulate the tubing clean. POOH w/tubing to 7,704'. Spot a 25 sx Class "H" cement in a balance plug to the EOT. Slowly POOH laying down 10 joints of tubing. Reverse circulate the tubing clean. POOH w/tubing to 7,704'. Spot a 25 sx Class "H" cement in a balance plug to the EOT. Slowly POOH laying down 10 joints of tubing. Reverse circulate the tubing clean. POOH w/tubing to 7,704'. Spot a 25 sx Class "H" cement in a balance plug to the EOT. Slowly POOH laying down 10 joints of tubing. Reverse circulate the tubing clean. POOH w/tubing to 7,704'. Spot a 25 sx Class "H" cement in a balance plug to the EOT. Slowly POOH laying down 10 joints of tubing. Reverse circulate the tubing clean. POOH w/tubing to 7,704'. Spot a 25 sx Class "H" cement in a balance plug to the EOT. Slowly POOH laying down 10 joints of tubing. Reverse circulate the tubing clean. POOH w/tubing to 7,704'.
- 18. PU and TIH w/2,400' of yellow band 2 3/8", J-55, 8rd tubing. Circulate hole with FSW until clean. Pressure test casing to 4,000 psig (51% of rated burst) f/15 minutes. Bleed off pressure.
- 19. POOH standing back tubing.
- 20. MIRU electric line unit. Run CBL/VDL/GR from PBTD to 200' above TOC. If bond is unacceptable notify OKC ASAP and a squeeze cementing procedure will be issued. If the bond is acceptable rig up a full 3000 psi lubricator. Perforate Delaware "A" formation at the following depths:

2180 - 2198'	2 jspf	37 shots
2206 - 2225'	2 jspf	39 shots
2239 - 2254'	2 jspf	31 shots

Correlate depth with Long Spaced Sonic Log of 3/30/94. RDMO electric line unit.

- 22. MIRU BJ Services. Frac Delaware perfs as per BJ Services procedure.
- 23. Flow back well for one hour at 1 bpm. Shut well in overnight.
- 24. TIH w/tubing and bailer and clean out casing to PBTD. POOH and lay down bailer.
- 25. TIH w/BP 30' mud anchor, 4' perf'd sub, SN and tubing to 2,300'. PU and TIH with a 1/1/2" pump on 7/8" Norris 78 rod string. Set pump load and test tubing. Hang off rods.
- 26. MIRU pumping unit w/gas engine.
- 27. Put well to sales.



Inex172.sch