Form 316i.*5 (November 1994)	ED STATES T OF THE INTEI					FORM APPROVED VISIOD Set Bureau No. 1004-0135 Expires July 31, 1996					
	BUREAU OF L	BUREAU OF LAND MANAGEMENT			1st Str		5 Lease Serial No				
	SUNDRY NOTICES	AND REPORTS (ON WEL	_{LS} A rtes ia	a, NM	88210	203 158	> N/N	-0468	<u>'6</u>	
	o not use this form for p andoned well. Use Form						6. If Indian, A	Allottee or T	lribe Name		
SUBMIT IN TRIPLICATE – Other instructions on reverse side							7. If Unit or CA/Agreement, Name and/or No. CA NM 71134				
Type of Well Oil X Gas Well Well Name of Operator	Qther	A					8. Well Name and No. BRIGHT FEDERAL 2 GAS COMP				
KERR-MCGEE OIL &	GAS ONSHORE LLC						9. API Well N				
3a. Address P.O. Box 809004, Dallas, TX 75380-9004				3b. Phone No. ((ifiguade area code) 972 715) (4520				30-015-28556 10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, S	ec., T., R., M., or Survey Descrip		10/12 / 14		tist<u>4</u>	2	INDIAN BAS			Ja	
UT. & 1650 F&L & SEC. 21-T21S-R23E		• 3		a Ali anti Ali t		11. County of EDDY	r Parish, Sta	ate NM			
12.	CHECK APPROPRI	ATE BOX(ES) TO I	NDICATE	NATURE OF	NOTICE,	REPORT.	OR OTHER D	ATA			
TYPE OF SU	JBMISSION		TYPE OF ACTION								
X Notice of I	Intent	X Acidize		Deepen Fracture Treat	X	Production Reclamatio	(Start/Resume)		ater Shut-Off 11 Integrity		
Subsequent Report		Casing Repair New Construction Recomple Change Plans Plug and Abandon Tempora					lete Other				
		Convert to Injec		Plug Back		Water Disp					
If the proposal is to c Attach the Bond under following completion of testing has been court	Commpleted Operation (clear leepen directionally or recomp r which the work will be per of the involved operations. If oleted. Final Abandonment N l site is ready for final inspection	formed or provide the the operation results in otices shall be filed or	Bond No.	on file with E	neasured and BLM/BIA. I r recompletio	Required su	ibsequent reports w interval, a Fo	s shall be orm 3160-4	filed within 4 shall be fi	30 days led once	
CURRENT WELL S		TIVE IS DRILL	OUT CIB	P AND ACI	DIZE AT	HIGH R	ATE. PLAC	E WELL	ON HIGH	I	
6 DC'S 2 7/8"	DURE: MIRU WO RIG WS TO CIBP @ 7100 & ACIDIZE UPPER P	'. CIRC HLOE W	1/ 7% KC	L, DRILL	CIBP, C	IRC WEL	L CLEAN, T	E. PU & TOH. SERVIC		RB,	
	OUDED SUB PUMP ON : WELL ON PRODUCTIO		80 IPC P	PRODUCTION	I STRING	. SET	PUMP @ APF	ROX.	7530'.		
ATTACHMENT	-S:						AL SEAD RESOURCE	2000 MAR - 7 1	RECEIVE		
				<u></u>			SOURC		VE		
14. I hereby certify that the for Name (Printed/Typed)	_		Tit				25	0:2	U		
	VEORES				TECHNIC		YST A			<u> </u>	
	tre		Da		03/03/00						
	TH	S SPACE FOR FE	DERAL	OR STATE	OFFICE	USE					
Approved by (OPIG	SGD.) DAVID F.	ALASS	ne		<u> i fnq</u> i	NFER		Date M	AR 09	2000	
Conditions of approval, if a certify that the applicant he	SGD.) DAVID R any, are attached. Approval olds legal or equitable title t ant to conduct operations therec	of this notice does not those rights in the s	warrantar ubject lease	Office		4 V 82 10 4 C					
Title 18 U.S.C. Section 10	001, makes it a crime for an	y person knowingly an	nd willfully	to make to a	ny departme	nt or agen	cy of the Unite	ed States a	my false, fic	ctitious of	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and wintury to make to any department of agency of the order of any matter within its jurisdiction.

PERMANENT ZERO POINT: KB - 13.0' ABOVE GROUND LEVEL @ 3922' MECHANICAL DETAILS COLLAPSE BURST 7100' (CIBP) 2020 TOTAL DEPTH: TOC 3520 CURRENT PBTD: 3270 SEAT SURF GRADE 4360 4320 WEIGHT CASING DETAILS 4980 SIZE K55 4000' 36# 9 5/8" K55 7700' 23.0# K55 SURFACE 7" PRODUCTION CSG 26.0# NONE CLEAN OUT WELLBORE BY DRILLING OUT CIBP. ACIDIZE AT TUBING: HIGH RATE. PUT ON TEST SUB AND EVALUATE FOR NONE CURRENT COMPLETION: WELL TA'ED PACKER: OBJECTIVE: PRODUCTION. Safety and the environment are top priority! 1. MIRU WO RIG. ND TREE, NU BOP'S. TEST BOP'S TO 300 PSI LOW AND 3500 PSI HIGH. 2. PU & TIH W/ RB, 6 DC'S AND 2 7/8" 6.5# L80 PLASTIC COATED EUE TBG TO CIBP @ PROCEDURE: TU & IIIA WI KD, O DU S AIND 2 110 O.J# LOU FLASTIC CUATED EVE IDU TU CI 7100 FT. CIRC HOLE WI 7% KCL. DRILL OUT CIBP. CIRC WELL CLEAN. TOH. 3. RU BJ SERVICES. ACIDIZE THE UPPER PENN PERFS 7140-7478' DOWN 7" CASING @ KU BI SERVICES. ACIDIZE THE UFFER FEININ FERTS /140-1410 DUWIN / CASIN 60-80 BPM. ACID TO BE PUMPED AS FOLLOWS PER ATTACHED BJ PROPOSAL: B. 10000 GALS 80 QUALITY N2 FOAM, W/ 100 BIOSEALERS A. 12000 GALS SLICK WATER D. 10000 GALS 80 QUALITY N2 FOAM, W/ 125 BIOSEALERS C. 40000 GALS 15% HCL NEFE F. 10000 GALS 80 QUALITY N2 FOAM, W/ 125 BIOSEALERS E. 40000 GALS 15% HCL NEFE G. 40000 GALS 15% HCL NEFE H. 12053 GALS NITRIFIED SLICK WATER

Bright Federal #2 Procedure Feb 7, 2000

•.

EST PUMP TIME 1 HR 19 MINUTES MAX RATE 3160 PSI

4. RD BJ SERVICES. RIH W/ ESP SHROUDED TEST SUB(TD 600-800) PER ATTACHED ESP RECOMMENDATION ON 2-7/8", 6.5#, L-80 IPC PRODUCTION STRING. SET PUMP DEPTH AT APPROX. 7530 FT.





RECEIVED In HA -TI A IP 23 In HA -TI A IP 23