R Cud

c151

Form 3160-5 (June 1990) Do not use this fo	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. NM LC 070409 6. If Indian, Allottee or Tribe Name 7. If Unit or CA, Agreement Designation			
1. Type of Well				
Oil Gas Well Well	Other	30,10111215141516	8. Well Name and No.	
2. Name of Operator			Avalon Federal No. 2	
Fasken Oil and Ran	9. API Well No.			
3. Address and Telephone N 303 W. Wall, Suite 1	30-015-29730			
4. Location of Well (Footage	10. Field and Pool, or Exploratory Area Wildcat 11. County or Parish, State Eddy County, NM			
2080' FSL, 750' FWI				
I2. CHECK A	PPROPRIATE BOX	B) TO INDICATE NATURE OF NOTICE, REPOR	T, OR OTHER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION		
Notice of	Intent	Abandonment	Change of Plans	
Final Abandonment Notice		Recompletion Plugging Back	New Construction	
		Casing Repair Altering Casing Other	Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Fasken Oil and Ranch, Ltd. proposes to recomplete the Avalon Federal No. 2 into a Wildcat pool in the Bone Spring formation. Please see the attached procedure for complete details.

14. I hereby certify that the foregoing to true and correct Signed	Title _	Regulatory Affairs Coordinator	Date	11/5/2002
(This space for Federal or State office use) (ORIG. SGD.) ALEXIS C. SWOBOD/ Approved by Conditions of approval, if any:	A Title	PETROLEUM ENGINEER	Date	NOV 07 2002

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See instruction on Reverse Side

Fasken Oil and Ranch, Ltd. Avalon Federal No. 2 2080' FSL & 750' FWL Sec 1, T21S R25E Workover Procedure AFE 626

OBJECTIVE:	Recomplete to Bone Spring
WELL DATA:	
13-3/8" 48# H-40 casing:	Set at 473', cement circ.
9-5/8" 36# J-55 casing:	Set at 2003' cement circ.
5-1/2" 17# N-80 casing.	Set at 10,593' DV @ 7276', TOC @ 720'. Marker Joint 7.73' @ 9698'.
Packer:	5-1/2"x2-3/8"Arrowset 1X 10K Set at 9650' w/TOSSDw/1.781' frac hardened "F" profile
Tubing:	299 jts 2-3/8" EUE 8rd N-80 Set at 9650'
Perfs	Atoka: 9731'-9737' 4 jspf 0 deg ph; Morrow: 10,406'-10413' Total 35 holes (13 0.23" 45 deg ph + 22 0.35" 0 deg ph)
KB:	13'
TD	10,600'
PBTD:	10,340': 10,375' CIBP w/35'Class "H" cmt, 10,545' FC

- 1. RUPU. Kill well with 40 bbls 3% KCL water containing packer fluid and 0.5 gpt ClayMaster 5C. Set test tank.
- 2. ND Wellhead. NU BOP.
- 3. Release packer and POW w/2-3/8" 4.7#/ft EUE 8rd N-80 tubing, TOSSD and 5-1/2" Arrowset packer.
- 4. RU wireline company. RU 3000 psi lubricator. Run 5-1/2" 17#/ft CIBP on wireline and set at 9,700'. Dump 35' Class "H" cement on CIBP for PBTD 9,665'. RD wireline company.
- 5. RIW w/ SN and 2-3/8" 8rd EUE N-80 tubing to PBTD 9665'.
- 6. Circulate well with 3% KCL water spotting 225 bbl 10 ppg gel laden mud.
- 7. Pull tubing laying down to +/-7570', spot 25 sx class "C" neat cement plug 7570'-7317' (per NMOCD Van Barton 11-4-02)).
- 8. Pull tubing laying down to +/-5400', spot 25 sx class "C" neat cement plug 5400'-5147'.
- Pull tubing laying down to 3605'. Circulate well with 80 bbls 3% KCL water containing 0.5 gpt ClayMaster 5C. Test casing to 2000 psi. Spot 250 gal 15% NEFE HCL acid 3605'-3349'. POW w/tubing and SN.
- 10. RU wireline with 3000 psi lubricator. Perforate Bone Spring Dolomite at 3590'-3620' with 1 spf, total 1 holes 60 deg phased with 4" casing gun by Schlumberger Platform Express Three Detector Litho-Density Compensated Neutron/GR log dated December 4, 1999. RD wireline company.
- 11. Displace spot acid via casing.

- 12. RIW w/5-1/2"x2-3/8" Arrowset I 10K packer with wireline re-entry guide, TOSSD w/1.781" "F" profile and 2-3/8" 4.7#/ft EUE 8rd N-80 tubing. Set packer at +/-3550'.
- 13. Swab and evaluate.
- 14. If additional stimulation necessary, RU BJ Services. Install tree saver. Trap 2000 psi on annulus. Treat perfs 3590'-3620' with 3000 gal NEFE 15% HCL acid dropping 60 1.3 sp. gr. RCNBS evenly spaced. Flush with 3% KCL water. Max pressure 1300 psi (0.8 psi/ft estimated frac gradient). BJ Additives are:

0.5 gal/M Clay Master-5C 2 gal/M FAW-18w, surfactant 2 gal/M NE-13, Non-emulsifier 1 gal/M CI-27, organic inhibitor 6 gal/M Ferrotrol-270L 2 gal/M Ferrotrol-271L Flush with 3% KCL water containing and NE-13 surfactant.

- 15. Swab acid and load water and evaluate whether to install pump equipment.
- 16. Release packer and POW w/2-3/8" tubing and packer.
- 17. RIW w/SN, 2-3/8"x4' perf sub, 10 jts 2-3/8" 8rd EUE N-80 tubing, 5-1/2" TAC, and 2-3/8" 8rd EUE N-80 tubing landing SN at +/-3650' (below bottom perf).
- 18. ND BOP, install tubing hanger and pumping tee.
- 19. RIW w/ insert pump and 76-rod string.
- 20. Hang well on and check pump action.
- 21. RDPU.

22. Put well on pump.

cwb 11-4-02 (avalon2 afe626 11-4-02.doc)