

Preston Fed #25
660FSL & 2310 FWL
Sec. 34-T20S, R23E
Eddy County, New Mexico

SQUEEZE / CEMENT

1. MERS Pulling unit. Blow well to pit & lead tubing w/ 2% KCL water. NU BOP.
2. Wireline set CEMENT RETAINER AT 6840'. Load 4 1/2" casing w/ 2% KCL water.
3. Pick up 2 3/8" work string & TIE & string into Retainer at 6840'. Establish injection rate into PERFS in 4 1/2" drill FROM 8128-38, 8158-78
4. mix & Pump 150 SX class H cement + 4 1/10% FL. followed by 125 SX class H neat cement. Pump cement to Retainer at 6840' & string out of Retainer, OR obtain squeeze pressure and string out of Retainer, whichever comes first.
5. Circulate casing clean. TOH & lay down 2 3/8" work string.