		()
Submit 3 Copies to Appropriate	State of New Mexico Energy, Minerals and Natural Resources Departm	Form C-103 Revised 1-1-89
District Office DISTRICT I	OIL CONSERVATION DIVISION	WELL API NO.
P.O. Box 1980, Hobbs NM 88241-1980	2040 Pacheco St.	30-015-31267
DISTRICT II	Santa Fe, NM 87505	5. Indicate Type of Lease
P.O. Drawer DD, Artesia, NM 88210		STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No.
	TICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PE	OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A RVOIR. USE "APPLICATION FOR PERMIT" C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
DIFFERENT RESE		Indian Hills Unit
1. Type of Well:		Indian Hills Unit
OIL GAS WELL	CTHER OTHER	
2. Name of Operator		8. Well No.
arathon Oil Company		# 28
3. Address of Operator		9. Pool name or Wildcat
0.0. Box 552 Midland, TX	79702	Indian Basin Upper Penn. Assoc.
4. Well Location Unit Letter "P" 21	8' Feet From The South Line and6	60' Feet From The East Line
Section 16	Township 21-S Range 24-E	NMPM Eddy County
	10. Elevation (Show whether DF, RKB, RT, GR, et G.L. 4014	tc.)
EMPORARILY ABANDON	CASING TEST AND	
12. Describe Proposed or Completed Op	perations (Clearly state all pertinent details, and give pertinent of	
 Describe Proposed or Completed Ogwork) SEE RULE 1103. 	perations (Clearly state all pertinent details, and give pertinent of for subsequent report to Form C-103.	dates, including estimated date of starting any proposed
 12. Describe Proposed or Completed Opwork) SEE RULE 1103. Please see attachment I hereby certify that the information above in the information above in the information. 	perations (Clearly state all pertinent details, and give pertinent of for subsequent report to Form C-103.	dates, including estimated date of starting any proposed NOV 2000 RECEIVED OCD - ARTESIA Startes bzez zzł.zolow NOV 2000
 12. Describe Proposed or Completed Orwork) SEE RULE 1103. Please see attachment 	perations (Clearly state all pertinent details, and give pertinent of for subsequent report to Form C-103.	dates, including estimated date of starting any proposed NOV 2000 RECEIVED OCD - ARTESIA NOV 2000 RECEIVED OCD - ARTESIA DATE <u>11/03/00</u>
 12. Describe Proposed or Completed Opwork) SEE RULE 1103. Please see attachment I hereby certify that the information above is SIGNATURE	perations (Clearly state all pertinent details, and give pertinent of for subsequent report to Form C-103.	dates, including estimated date of starting any proposed NOV 2000 RECEIVED OCD - ARTESIA Startes bzez zzł.zolow NOV 2000
 12. Describe Proposed or Completed Opwork) SEE RULE 1103. Please see attachment I hereby certify that the information above is SIGNATURE	perations (Clearly state all pertinent details, and give pertinent of for subsequent report to Form C-103.	dates, including estimated date of starting any proposed

 \bigvee

Indian Hills Unit # 28 218' FSL & 660' FEL Sec. 16, T-21-S, R-24-E U.L. "P" API # 30-015-31267 Eddy Co. N.M.

Drill and set 40' 20" conductor pipe cement to surface. Nipple up rotating head, P.U. BHA. Alert OCD @ 9:15 AM CST. Air drill f/ 72' to 1637. Air mist drill f/ 1637' to 1804' w/ air. T.D. surface hole.R.u csg. crew, ran 40 jts. 13-3/8" 54.50# csg. to 1784'. R.U. HES pummp 10- bbls. Water spacer 100 sks. Diamond seal, 100 sks. Premium plus thix w/ 1% com. A .25% Com B 2% cacl2, .5# Fo. And 5# gilsonite. Tailed with 300 sks. Premium Plusw/ 2% cacl2. Circ. 60 sks. diamond seal and 20 sks.good cement to pit. WOC 18- hrs. Test csg, to 1000# OK. Drill out float and cement in shoe joint. Drill from 1804' to 3800'. Pick up MWD & BHA Orient motor slide drill 3800' to 7977.' Circ. And survey @ 7977'.TIH w/ new bit & new BHA. Drill from 7977' to to 8052 w/ 60 bph loss. Drill f/ 8052' to 8870, pump 90 bbl sweep & circ. TOH w/ BHA, R.U Schlumberger run Platform Express w/ HRLA & NGT, FMI, from 8806 T.D. to surface. R.U. Rogers csg. crew, ran float shoe, 1-jt, float collar 32 jts.9-5/8" csg, 43.50# L-80 and 9-5/8" 40# K-55. Set ECP-DV @ 7414-7427. Ran casing to 8870'. Cement casing in 2- stages.

First stage: Pump 100000 scf N2 725 sks. Premium cmt. w/ 150 scf/ bbland 1% Zone sealant. Set ECP w/ 3100#, dropped bomb, open D.V. tool. Circ. Nitrogen and 75 sks. cmt to pit.

Second stage w/ 1360 sks. Interfill"C" w/ additives followed by 225 sks. Prem,ium Class "H" cmt.

Circ. 180 sks to pit. N.D. BOP, set csg. slips.W.O.C. 12- hrs. TIH w/ 8-1/2" bit, drill cmt and wiper plug. Pressur test casing to 1000# O.K. Washed/ drilled cmt. to float collar and circulated. T.O.H. w/ bit laying dn. Drill pipe. N.D. BOP stack, Release rig 311 @ 12:00 Noon 11/02/00.