|  | -  |  |   |
|--|--|--|---|
| Form 3160-5<br>(June 1990)   | TED S DEPARTMENT OF<br>BUREAU OF LAND  | TATES N.M. Oil Cons. L.vision<br>THE INTERIOR<br>MANAGEMENT S. 1st Street  | Explices. March 51, 1995  |
|  |  | Artosia NM 88210-28  | 5. Lease Designation and Serial No.<br>NM- 0400512A   |
| Do not us  | SUNDRY NOTICES AND I<br>se this form for proposals to drill or to<br>Use "APPLICATION FOR PE   | 6. If Indian, Allottee or Tribe Name   |   |
| SUBMIT IN TRIPLICATE   |  |  | 7. If Unit or CA, Agreement Designation<br>27324  |
| 1. Type of We  | Gas  |  | 8. Well Name and No.  |
| 2. Name of O   |  | ICA 31 Fed No. 1   |   |
| Nadel an   | d Gussman Permian, L.L.C.  | OGRID# 155615  | 9. API Well No.<br>30 - 015 - 31587   |
|  | arienfeld, Suite 508, Midland, TX 79701  | 10. Field and Pool, or Exploratory Area  |   |
| 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)<br>1800' FSL & 840' FWL, unit letter L<br>Sec. 31 - T20S - R27E |  |  | Avalon Morrow   |
|  |  |  | 11. County or Parish, State   |
|  |  |  | Eddy Co., NM  |
| 12.  | CHECK APPROPRIATE BOX(s) TO IN   | IDICATE NATURE OF NOTICE, REPORT   | OR OTHER DATA   |
|  | TYPE OF SUBMISSION   | TYPE OF ACTION   |   |
|  | Notice of Intent   | Abandonment Recompletion   | Change of Plans   |
|  | Subsequent Report  | Plugging Back  | New Construction  |
|  |  | Casing Repair  | Water Shut-Off  |
|  | Final Abandonment Notice   | Altering Casing  | Conversion to Injection   |
|  |  | Other  | Dispose Water     Note: Report results of multiple completion on Well     Completion or Recompletion Report and Log form.)  |
| Notice of  | ly drilled, give subsurface locations and measured and i<br>setting intermediate casing:<br>Drilled to 2000'. RIH with 45 joints of 8-5/8".  | tinet details, and give pertinent dates, including estimated date<br>true vertical depths for all markders and zones pertinent to this   | of starting any proposed work. If well is work.)*   |
|  | thixotropic and 400 sx 65:35 Class C with r  | , 24#, J55 STC casing and set at 2000'. RU BJ ar<br>no returns. BLM on location to witness casing runr<br>with 1" string and tagged @ 611'. Cemented 8-5/4   | ning and cementing. Ran   |
| 03/26/01   | thixotropic and 400 sx 65:35 Class C with r<br>temp survey and found TOC at 500'. RIH<br>POOH with 1" string and WOC. RIH with 1"<br>Pumped 136 sx and circulated 12 sx to the   | no returns. BLM on location to witness casing runr<br>with 1" string and tagged @ 611'. Cemented 8-5/4<br>and tagged at 430'. Pumped 50 sx and POH. Rill<br>pit. BLM on location to witness 1" operations. ND<br>Tested hydril, rams, accumulator and choke mar  | hing and cementing. Ran<br>B" through 1" with 50 sx class C.<br>H with 1" and tagged up at 375'.<br>BOP, set slips and cut off casing.  |
|  | thixotropic and 400 sx 65:35 Class C with r<br>temp survey and found TOC at 500'. RIH v<br>POOH with 1" string and WOC. RIH with 1"<br>Pumped 136 sx and circulated 12 sx to the<br>NU BOP's, RU flowline and Mann Welding<br>location to witness. TIH with bit, packed BH   | no returns. BLM on location to witness casing runr<br>with 1" string and tagged @ 611'. Cemented 8-5/4<br>and tagged at 430'. Pumped 50 sx and POH. Rill<br>pit. BLM on location to witness 1" operations. ND<br>Tested hydril, rams, accumulator and choke mar  | hing and cementing. Ran<br>B" through 1" with 50 sx class C.<br>H with 1" and tagged up at 375'.<br>BOP, set slips and cut off casing.<br>hifold to BLM specs with BLM on<br>tested shoe to 500 psi - OK. |
| 03/27/01<br>14. I hereby a<br>Signed   | thixotropic and 400 sx 65:35 Class C with a<br>temp survey and found TOC at 500'. RIH<br>POOH with 1" string and WOC. RIH with 1"<br>Pumped 136 sx and circulated 12 sx to the<br>NU BOP's, RU flowline and Mann Welding<br>location to witness. TIH with bit, packed BH<br>Tagged cement in casing at 1918'. Tested of<br>Resumed drilling new 7-7/8" hole.         | no returns. BLM on location to witness casing runr<br>with 1" string and tagged @ 611'. Cemented 8-5/4<br>and tagged at 430'. Pumped 50 sx and POH. Ril<br>pit. BLM on location to witness 1" operations. ND<br>. Tested hydril, rams, accumulator and choke mar<br>IA and drill collars.<br>casing to 1000 psi - OK. Drilled through shoe and the<br>ACCEPTED FOR               | hing and cementing. Ran<br>B" through 1" with 50 sx class C.<br>H with 1" and tagged up at 375'.<br>BOP, set slips and cut off casing.<br>hifold to BLM specs with BLM on<br>tested shoe to 500 psi - OK. |
| 03/27/01<br>14. I hereby a<br>Signed   | thixotropic and 400 sx 65:35 Class C with a<br>temp survey and found TOC at 500'. RIH with 1"<br>POOH with 1" string and WOC. RIH with 1"<br>Pumped 136 sx and circulated 12 sx to the<br>NU BOP's, RU flowline and Mann Welding<br>location to witness. TIH with bit, packed BH<br>Tagged cement in casing at 1918'. Tested of<br>Resumed drilling new 7-7/8" hole. | no returns. BLM on location to witness casing runr<br>with 1" string and tagged @ 611'. Cemented 8-5/4<br>and tagged at 430'. Pumped 50 sx and POH. Rife<br>pit. BLM on location to witness 1" operations. ND<br>. Tested hydril, rams, accumulator and choke mar<br>IA and drill collars.<br>casing to 1000 psi - OK. Drilled through shoe and the<br>ACCEPTED FOR<br>APR 0 5 2 | hing and cementing. Ran<br>B" through 1" with 50 sx class C.<br>H with 1" and tagged up at 375'.<br>BOP, set slips and cut off casing.<br>hifold to BLM specs with BLM on<br>tested shoe to 500 psi - OK. |

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



APR 03 2001 BLM BLM