Submit 3 Copies to Appropriate District Office	State of New M Energy, Minerals and Natural R		CIST	Form C-103 Revised 1-1-89			
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATIO 2040 Pacheco St. Santa Fe, NM 8		WELL API NO. 30-015-3224	x			
<u>DISTRICT II</u> P.O. Drawer DD, Artesia, NM 88210		222322 S	sIndicate Type of Lea				
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	です。 (1) (1) (1) (1) (1) (1) (1) (1)		•State Oil & Gas Leas L-3604				
SUNDRY NOTI (DO NOT USE THIS FORM FOR PRO DIFFERENT RESER (FORM C-	7Lease Name or Unit	Agreement Name					
iType of Well: OiL GAS WELL X WELL	OTHER		Lost Tank 3	5 State			
2Name of Operator Pogo Producing Company							
Address of Operator P. O. Box 10340, Midland, TX 79702-7340			Pool name or Wildcat Lost Tank Delaware				
4Well Location Unit Letter <u>F</u> : <u>1930</u>	Feet From The North	Line and 2030	Feet From The	West Line			
Section 35		Range 31E	_{ммрм} Eddy	County			
10Elevation (Show whether DF, RKB, RT, GR, etc.) 3528 ' GR							
¹¹ Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data							
NOTICE OF INTENTION TO: SUB			SEQUENT RE	PORT OF:			
	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING			
	CHANGE PLANS	COMMENCE DRILLING OF	PNS. X	PLUG AND ANBANDONMENT			
PULL OR ALTER CASING		CASING TEST AND CEME	NT JOB				
OTHER:		OTHER:					

¹²Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spud & Set Surface Csg – MIRU Patterson #54. Spud well @ 2200 hrs 09/12/02. Drid 17-1/2" hole to 829'. TD reached @ 08:00 hrs 09/14/02. Ran 19 jts 13-3/8" 48# H-40 LT&C csg. TPGS @ 829'. BJ cmt'd w/ 700 sks 65:35 POZ @ 12.8 ppg followed by 200 sks CI "C" + 2% CaCI @ 14.8 ppg. Circ 180 sks to surface. Plug down @ 15:00 hrs 09/14/02. WOC 18 hrs. Make cut-off. Weld on WH. NU BOP's & test ok.

24 Hours for R-111-P

Intermediate Csg – Drld 11" hole to 4100'. TD reached @ 16:45 hrs 09/21/02. Ran 95 jts 8-5/8" 32# J-55 ST&C csg. Cmt 1st stage w/ 570 sks 65:35 POZ @ 12.4 ppg followed by 200 sks Cl "C" + 1% CaCl @ 14.8 ppg. Circ 48 sks to surface. Cmt 2nd stage w/ 670 sks 65:35 POZ @ 12.4 ppg followed by 100 sks Cl "C" + 1% CaCl @ 14.8 ppg. Lost returns on 2nd stage. WOC. Ran temp survey. TOC @ 2200'. Perf 4 holes @ 2150. Circ thru perfs. Make cut-off. Install WH. NU BOP. Cmt sqz perfs w/ 600 sks "C" Lite tailed w/ 100 sks "C" w/ 1% CaCl. Lost returns. Ran temp survey. TOC @ 1400'. Perf 4 sqz holes @ 1300'. Pump 500 sks "C" w/ 2% CaCl. Lost returns. Ran temp survey. TOC @ 1400'. Perf 4 sqz holes @ 1300'. Pump 500 sks "C" w/ 2% CaCl. Lost returns. Ran temp survey. TOC @ 1100'. Perf 4 sqz holes @ 1050. Cmt w/ 300 sks "C" Lite w/ 5% NaCl & tailed w/ 100 sks "C" w/ 2% CaCl. Circ 107 sks excess cmt. WOC. DO cmt to 2085. Test csg to 500# ok. NU BOP's & test to 3000# ok.

I hereby certify that the information above is true and complete to the best of m SIGNATURE	iy knowledge a		DATE	10/23/02
TYPE OR PRINT NAME Cathy Tomberlin		915-685-8100 TELEPHONE NO.		
(This space for State Use) APPROVED BY RECEND Chily BAL CONDITIONS OF APPROVAL, IF ANY:	TITLE		DATE	OET 2 3 2002