

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN
(Other inst.
verse side)PLICATE*
ons or re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-03814-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER Shut In	7. UNIT AGREEMENT NAME Bandana Point Unit
2. NAME OF OPERATOR Humble Oil & Refining Company	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR P. O. Box 1600, Midland, Texas 79701	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 750' from South Line and 1900' from the East Line, Section 13, T-23-S, R-23-E, NMPM, Eddy Co., New Mexico.	10. FIELD AND POOL, OR WILDCAT Bandana Point Penn
14. PERMIT NO. -	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4026DF
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 13, T-23-S, R-23-E
	12. COUNTY OR PARISH Eddy
	13. STATE N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Note: Gel mud must be placed between all plugs.

1. Rig up and kill well with water.
2. Unseat hookwall packer and circulate water around.
3. If hole stands full OK - lower tubing two joints and spot 40 sacks sloset cement on bottom 9800-9500'. If hole does not stand full, leave tubing at 9726 feet and spot the 40 sx. sloset plug. Displace hole with gel mud.
4. Pull tubing. Run free point.
5. Cut 5-1/2" casing at free point and pull.
6. Spot cement plug across cut with 30 sx. slo set;
- 6a. Spot 150' Cement plug 3100' to 2950' with 75 sx. sloset.
7. Spot cement plug 2325 to 2225' w/50 sx. sloset.
8. Spot 10 sx. plug in surface and cut off wellhead.
9. Install dry hole marker.

Verbally approved by Jim Knauf, U.S.G.S., District Engineer, 4-21-67.

RECEIVED

APR 28 1967

O. C. C.

ARTISIA, OFFICE
Agent

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

4-24-67

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APR 21 1967

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.