		EPAR INT OF THE		(Other instr bs on r verse side)	Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SEBIAL NO.
	SUNDR	GEOLOGICAL SUI		WELLS STER	USA NM 0556765 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	(Do not use this form for proposals to drill or to deepen or plug back 12 a different teservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)				
	OIL GAS WELL A	OTHER Shut In		100 1057	7. UNIT AGREEMENT NAME Bandana Point Unit 3 8. FARM OB LEASE NAME
	Humble Oil and Refining Compan 3. ADDRESS OF OPERATOR				9. WELL NO.
	P. O. Box 1600, Midland, Texas 79701 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)				10. FIELD AND POOL, OR WILDCAT
	At surface 750' from South Line and 1900' from East Line, Section 13, T-23-S, R-23-E, NMPM, Eddy Co., New Mexico				Bandana Point Penn 11. SBC., T., B., M., OR BLK. AND SUBVEY OR AREA Sec. 13, T-23-S, R-23-E
	14. PERMIT NO.	15. ELEVATIONS (Show 4026 D		, etc.)	12. COUNTY OF PARISH 13. STATE Eddy New Mexico
	16. Check Appropriate Box To Indicate Nature of Notice, Report, or C				
					DQUENT REPORT OF:
	TEST WATER SHUT-OFF Fracture treat Shoot or acidize Repair well	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON [‡] CHANGE PLANS		WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING	REPAIRING WELL ALTERING CASING ABANDONMENT*
	(Other)	······································		Completion or Recom	ts of multiple completion on Well apletion Report and Log form.)
2. 3. 4. 5. 6. 1 7. 1 8. (9. (10. 2	 17. DESCRIBE PROPOSED OF CONFERENCE OFFERENCE OFFERENCE STATUS and give pertubent datas. Including estimated and on a starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markets and scores perturned to this work.) Well incapable of producing in paying quantities. Began abandonment 4-25-67. 1. Rigged up, bled well down and killed well with 170 bbls. brine. 2. Unable to unseat packer at 9726 ft. Started to pump 40 sx. cement into perforations at 9782-9796'. 3. Encountered a pressure surge to 3800 psi before cement cleared tubing causing tubing to split. Unbeknownst to operator, swab had been lost in tubing by contractor some years ago, and not reported. 4. Circulated as much cement as possible out of tubing (calculated hole in tubing to be between 7000-8000' based on circulating volumes) then released packer. 5. Attempted to pull tubing but found tubing stuck. Ban free point indicator and found tubing to cedures. 6. Ban impression block and found wire line cuttings at 9674. 7. For three days unsuccessfully attempted to find exact location of hole in tubing utilizing Otis Cut 2" tubing at 9640 and squeezed perforations 9782-9796 with 40 sx. of slo set cement, max. press. 2850. Left pressure on cement overnight. (Packer and 86' of tubing containing swab left in well). 6. Cut 2" tubing at 540'; spotted 12 sx. neat cement plug from 100' to surface, leaving an additional 9100' stuck 2" tubing in well from 540-9640'. 7. Tied on to 10-3/4-5-1/2" bradeghead outleft and pumped 850 sx. of neat cement into this casing annulus to 227' and into the 9-776' continued on attached on etteched on ettech				
· · ·	casing shoe. Max. pre 18. I hereby certify that the SIGNED	1 the the		ent	50 (7
	(This space for Federat			- NE	
	APPROVENCEN FILE APPROVENCENCE APPRO JUN 2 1 1967 JUN 2 1 1967 H. L. BEEKINIA T R. L. BEEKINIA T	DVAL, IF ANY :	TLE	everse Side	
	ACTING			n en	