

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-101
Supersedes Old
C-102 and C-103
Effective 1-1-65

MAY 1 1978

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR ANY OTHER PURPOSES. IT IS TO BE USED ONLY FOR THE PURPOSES SPECIFIED HEREIN. IT IS TO BE FILED IN THE OFFICE OF THE COMMISSIONER OF THE NEW MEXICO OIL CONSERVATION COMMISSION.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER	6. Name of Lease Holder Cities Service Company
2. Name of Operator P. O. Box 1919, Midland, Texas	7. Unit Agreement Name Spencer "A"
3. Address of Operator P. O. Box 1919, Midland, Texas	8. Well No. 1
4. Location of Well UNIT LETTER 0 660 FEET FROM THE South LINE AND 1980 FEET FROM East THE LINE, SECTION 30 TOWNSHIP 22S RANGE 27E NEPDA.	9. Field and Pool, or Wildcat So. Carlsbad (Strawn)
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☒ Abandon Morrow & Test Additional Strawn zone	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

T. D. 11,820' P.B. T. D. 11,764

1. MIRU pulling unit. Kill well w/2% KCL water. ND tree. NU BOP.
2. Release Baker Lok-Set packer @ 11,325' and release tubing from Baker Model D Packer @ 11,490'.
3. Set CIBP on wireline at approximately 11,350' to P&A Morrow. Dump 35' cement on top of bridge plug. New PBTD Should be 11,315'.
4. Set CIBP on wireline at approximately 10,390' to P&A Strawn. Dump 35' cement on top of bridge plug.
5. Circulate hole w/2% KCL water. Spot 50 gallons acetic acid 10,300 - 10,350'.
6. Perforate Strawn 10,323' to 10,331' using 4" casing gun and 2 shots/ft.
7. RIH w/muleshoed tubing sub and Baker Lok-Set packer on 2-3/8" Buttress tubing and set packer at approximately 10,250'. Swab well in.
8. Test well natural.
9. If necessary, acidize well.
10. Backflow treatment and test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Region Operation Mgr.</u>	DATE <u>April 28, 1978</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>DIRECTOR, DISTRICT II</u>	DATE <u>MAY 2 1978</u>
CONDITIONS OF APPROVAL, IF ANY:		