

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Alamosa, NM 88210

SUBMIT IN TRIPLICATE

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-027994-F

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

O'Neill Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

South Carlsbad Morrow

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Section 23, T23S, R26E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR
J.M. Huber Corporation

3. ADDRESS OF OPERATOR
1900 Wilco Building, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
1980' FNL & 1980' FEL, Section 23, T23S, R26E
Eddy County, New Mexico

14. PERMIT NO. 30-015-20740
Approved 9/7/72

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3268.6 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*


(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plug and Abandon Procedure:

1. RIH w/Freepoint tool and cut tubing at freepoint. POOH w/1½" tubing. (est. recovery 11,350')
2. RIH w/CIBP set above tbg stub place 35' cmt on top.
3. RIH w/2-7/8" tbg, tag TOC. PU & place 25 sx cmt plug 10,847-640'.
4. Find freepoint & cut off 5½" csg (est. 9800'). POOH w/5½" csg.
5. Place 50 sx cmt in & out of 5½" csg stub.
6. Place 60 sx cmt over interval 6930-6780'.
7. Place 75 sx cmt over 9-5/8" csg shoe 5460-5260'. Tag top of plug.
8. Place 55 sx cmt over interval 3300-3150'.
9. Place 50 sx cmt over interval 1950-1850'.
10. Find freepoint on 9-5/8" csg, cut & POOH w/9-5/8" csg (est. 1100').
11. Place 70 sx cmt in & out 9-5/8" csg plug. Tag top of plug.
12. Place 90 sx cmt over 13-3/8" csg shoe (650-550'). Tag top of plug.
13. Cut off 13-3/8" csg 3' below ground level & place 10' cmt in stub. Set D.H. marker.



18. I hereby certify that the foregoing is true and correct (915) 682-3794

SIGNED Robert R. Glenn TITLE District Production Manager DATE 5/16/86

(This space for Federal or State office use)
Orig: See

APPROVED BY _____ TITLE _____ DATE 5-23-86

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side