

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

C/SF

Open.

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

JUN 11 '90

WELL API NO.

30-015-20759

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Union Mead Com

8. Well No.

2

9. Pool name or Wildcat

Wolfcamp/Morrow

1. Type of Well:

OIL

WELL ☐

OAS

WELL ☒

OTHER

2. Name of Operator

Quinoco Petroleum, Inc.

3. Address of Operator

P. O. Box 378111, Denver, CO 80237

4. Well Location

Unit Letter N : 1880 Feet From The West Line and 660 Feet From The South Line

Section 4

Township 22S

Range 27E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3122.8' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Quinoco Petroleum plugged and abandoned the Union Mead Com #2 as follows:

4/16/90

1. MIRU pulling unit. Kill well w/10#/gal brine.

4/17-18/90

2. POOH w/2-7/8" & 2-3/8" tbg & three pkrs.

4/19/90

3. Tag CIBP @ 11,500', spot 10 sx cmt (TOC @ 11,325').

4. Dump 25 sx cmt @ 11,110', TOC @ 9,530'.

4/23/90

5. Cut 2-3/8" tbg @ 9,500', set CIBP @ 9,400' and dump 10 sxs cmt on top (TOC 9275').

4/24/90

6. Spot 80 sx class "H" cmt @ 8,970', TOC @ 8,622'.
(see back)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Holly S. Richardson

TITLE Sr. Ops. Eng. Tech.

DATE 6/1/90

(303)

TELEPHONE NO 850-6322

TYPE OR PRINT NAME Holly S. Richardson

(This space for State Use)

APPROVED BY Johnny Robinson

TITLE

DATE 10-29-90

CONDITIONS OF APPROVAL, IF ANY:

4/25/90

7. Spot 30 sx cmt @ 8,622', TOC @ 8,485'.

8. Work and stretch 7-5/8 29.7# csg, freepoint @ 5,800'. Cut, POOH & LD csg.

4/27/90

9. Spot 25 sx cmt @ 7,100', TOC @ 6,998'.

10. Spot 50 sx cmt @ 5,850', TOC @ 5,791'.

4/30/90

11. Spot 20 sx cmt @ 5,791', TOC @ 5,751'.

12. Spot 60 sx cmt @ 5,200', TOC @ 5,079'.

5/1/90

13. Pump 140 sxs cmt @ 2,080', TOC @ 2,005'.

14. Pump 100 sxs cmt @ 2,005', TOC @ 1,836'.

15. Pump 45 sxs cmt @ 383', TOC 298'.

16. Pump 10 sxs cmt @ 30', TOC @ surf.

5/2/90

17. Drill out cmt to 1,270', circ cmt to surf.

5/3/90

18. RIH w/gun and shoot squeeze holes @ 1,270'.

19. Set 10-3/4" cmt ret @ 1,220' (TP 1200 psi).

5/4/90

20. Pump 25 sxs Howco cmt on cmt retainer @ 1,220', TOC @ 1,160'.

21. Pump 40 sxs Howco cmt @ 383', TOC @ 283'.

22. Pump 110 sx cmt @ 333' between 10-3/4" & 13-3/8" csg.

5/5/90

23. Pump 70 sx cmt @ 90', TOC @ surf.

24. Weld on plate & install P&A marker, fill in collar & RD PU.