

DATE: Dec. 3, 1979

BOWDEN "25" FEDERAL COM #1

1. Move in 2-500 bbl frac tanks.
2. Squeeze the Atoka perforations @ 2210-226 with 75 sacks of Class "H" 1/4#/sx Floccel or set a CIBP 50' above Atoka perforations at 12,210-220 and dump 35' of cement on top of plug.
3. TIH with tubing to 9128' (75' below liner top @ 9053') spot a 25 sack Class "H" cement plug.
4. TOH with tubing standing back 4000'.
5. Rig up Wireline Company and determine freepoint and cut 7-5/8" casing at approx 3000' spot a 35 sack plug 50' inside 7-5/8" casing or deeper and 50' on top of stub. If the casing is cut off deeper well will need to set and additional 50 sack plug in the open hole at 3000'.
6. Spot a 65 sack plug 2214 to 2114 @ 100 foot plug.
7. Spot a 20 sack Class "H" plug at surface. (42' to 0)
8. Cut off Braidenhead and wellplate over casing and welded on dryhole marker.
9. Clean up location.

SUBMITTED BY: M. E. Carls

DEC 5 1979  
U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO