

loss of pressure; repressured to 5000# with loss of pressure; repressured to 5000# with same leak to both door seals of upper pipe rams bop. Tightened.

Test #15 Repeated test. Pressured to 4000# with same leak thru upper pipe rams. Operated rams and changed out joint of drill pipe.

START CHART #3

Test #16 Repeated test. Pressured to 50# with same leak.

---

Waiting on crew to remove upper pipe rams bop and install Hydril above blind rams bop.

START CHART #4

TESTING: Hydril with all inside valves closed next to stack.

Test #17 Pressured to 3800# with loss of pressure; repressured to 3800# and released pressure to 3000# with loss of approximately 100# during first thirteen minutes then leveling out for remaining one minute of test.

NO VISIBLE LEAK. PRESSURE LEVELING OUT TOWARDS APPROXIMATELY 2900#.

---

TESTING: Upper Kelly Cock with pressure applied at bottom of kelly.

Test #18 Pressured to 50# with leak thru upper kelly cock.

---

No delay was observed to operation of blowout control equipment at the conclusion of testing. Closures were made using closing unit pump only to the observed pressure of 1500# for test to ram type bops and 1500# for test to Hydril. Accumulators were pressured to 1500#