

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIP  
(Other instructions  
verse side)TE\*  
re-Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0539770

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ Dry Hole2. NAME OF OPERATOR  
HNG Oil Company3. ADDRESS OF OPERATOR  
Box 2267, Midland, Texas 797014. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

860' FNL &amp; 1980' FWL, Sec. 31, T-24-S, R-27-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3391' GR

7. UNIT AGREEMENT NAME

Coles "31" Federal

FARM OR LEASE NAME

Coles "31" Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Midland/Morrow

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREASec. 31, T-24-S, R-27-E,  
NMPM

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

Re-Plug Well

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

PURPOSE: To spot additional plugs in well and replace leaking surface plug.

PROCEDURE: 1. Dig out cellar, weld on casing head, install 5000# blowout preventor.  
2. Knock out surface plug and remove dry hole marker.  
3. Run 2-7/8" tubing to 3500'. Circulate hole with 10# gelled brine. POH.  
4. Run Halliburton 10-3/4" E-Z Drill SV retainer on tubing. Set at 2000'.  
5. Mix 200 sk. plug. Pump 170 sx. below retainer. Pull out, close valve.  
Dump 30 sx. above retainer. Plug from 2300' to 1950'.  
6. Spot 100 sk. surface plug from 200' to surface.  
7. Install dry hole marker, fill cellar and clean location.

RECEIVED

JUL 26 1976

O. C. C.  
ARTESIA, OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED

R. R. Frazier

TITLE District. Prod. Supt.

DATE 7-20-76

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side