

Form 3160-5
November 1983)
Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 70335

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Livingston Ridge Fed

9. WELL NO.

9

10. FIELD AND POOL, OR WILDCAT

Cabin Lake (Delaware)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 1, T-22-S, R-30-E

14. PERMIT NO.

30-015-21050

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

3337' GL; 3356' DF

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Convert to SWD

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 10-6-92 - RU RAM DDU. SITP 800#; SICP-500#; Bleed well into test tank 5 mins. ND wellhead and NU BOP. Release Pkr. & POOH w/2-7/8" tbg.
- 10-7-92 - POOH. 5-1/2 Baker LOC - Set Pkr. GIH w/5-1/2 CIBP and set @12,300' and GIH w/Dump bailer and place 5 sks Class H cmt. TOC 12,253'. GIH w/Bull plug - 1-2' Posted Sub and 271 jts. 2-7/8" 6.5 N-80 Workstring.
- 10-9-92 - PU 2-7/8" workstring to 10,300'. RU HOWCO & Spot 50 sks. Plug Class H. POOH w/10 stands. Reverse Circ. Close well in and Pressure test to 500 PSI for 15 mins. Okay. POOH w/72 stands.
- 10-10-92- POOH & LD 2-7/8" workstring. GIH & tag cement @ 9998. GIH w/7-5/8" CIBP and set 5000' and dump 8 sks Class H. TOC 4964'. GIH w/2-7/8" workstring to 4550'. Pump 400 gals 15% HCl Acid and spot 1500 gals. 20% Acetic Acid.
- 10-13-92- Perf. 7-5/8" csg. w/4" csg. gun 1JSPF: 3854-3920 - 67 Shots; 3936-4024 - 89 shots; 4318-4354 - 37 shots; 4364-4440 - 77 shots; 4456-4538 - 83 shots - Total 353 Shots.
- 10-14-92- GIH 2-7/8"tbg. Internally tested to 5000 psi and set Pkr. 3740'. Pump 35 bbls. P.W. and pump acid into 7-5/8" csg. perfs. 3584-4538 Release Pkr. POOH 2-7/8" workstring.

(Over)

18. I hereby certify that the foregoing is true and correct

SIGNED

L. M. Sanders

TITLE

Supv. Reg. Affairs

DATE

10/19/92

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

3197

Post ID-2
11-13-92

camp SWD

*See Instructions on Reverse Side

GIH W/7-5/8" Nickel plated and internally plastic coated LOC
Set pkr. and 2-7/8" on-off tool w/2.25 profile on 119 jts. 2-
7/8" 6.5 EUE L-80 tbq. ND BOP. Set pkr. 3758 and test tbq.
csg. to 500 psi for 30 mins. O.K.

10-15-92

Run BHP. 1880 PSI. Run Step Rate:

10-17-92

(1) 326 PSI 374 BPD: BHP 2339
(2) 503 PSI 566 BPD: BHP 2476
(3) 690 PSI 864 BPD: BHP 2740
(4) 654 PSI 1219 BPD: BHP 2782
(5) 690 PSI 1632 BPD: BHP 2808
(6) 706 PSI 2035 BPD: BHP 2808
(7) 745 PSI 2428 BPD: BHP 2836

Placed on SMD Service.

N:\RegPro\AFran\Cbnlk9.605