

June 14, 1974

AMOCO Production Company

Hobbs, New Mexico

Attn: Drilling Dept.

RE: BOP Test - Your Trails Canyon Unit #1

Gentlemen:

We made a hydrostatic pressure test to captioned blowout control equipment on June 13, 1974, and wish to advise the following:

At the conclusion of testing:

Hydril: Leak to lower Hydril seals (pressure on closing line to Hydril accumulator valve 2400#) - to be repaired or replaced as needed.

Valve: Leak thru check valve off stack on kill line with no pressure being applied - to be repaired or replaced as needed.

Separate tests were made at the pressure of 3100# to chokeline, choke-manifold, and to the valves and fittings off the bop stack proper. The pipe rams and approximately 3 ft. of 8 5/8" casing were tested to 2500#. The upper kelly cock was tested to 3000#.

There were no visible leak to items tested at the conclusion of testing other than as mentioned above.

No delay was observed to operation of blowout control equipment at the conclusion of testing. Closures were made using closing unit pump only to the observed pressure of 1500# for test to ram type bops and 2400# for test to Hydril. Accumulators were pressured