

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-22441
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name CITY OF CARLSBAD
2. Name of Operator THE EASTLAND OIL COMPANY	8. Well No. 1
3. Address of Operator P. O. DRAWER 3488, MIDLAND, TX 79702	9. Pool name or Wildcat HERRADURA BEND CHERRY CANYON
4. Well Location Unit Letter K : 2110 Feet From The SOUTH Line and 1980 Feet From The WEST Line Section 29 Township 22-S Range 28E NMPM EDDY County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3032' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CASING IN WELL CONSISTS OF:

- (A) 8-5/8" surface csg. @357'. Cemented w/250 sx circulated.
(B) 7" set @ 3266'. Cemented w/250 sx Class C.
(C) 4 1/2" set @3274'. Cemented w/200 sx light & 50 sx Class C circulated. Open Hole 3274-98'.
Plugging Procedure as follows:

1. Plug @3298' w/25 sx cement & tag.
2. Load Hole w/9.6# mud thru 2" tbg.
3. Plug @1455' w/25 sx across top of salt. 2090-2450
4. Plug @1071' w/25 sx across shoe & tag. 300-460
5. Plug @surface w/10 sx.
6. Set 4" X 4' marker & clean location.

Notify N.M.O.C.C. in sufficient time to witness
Plugging

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Travis Reed TITLE Production Superintendent DATE 10/13/93
TYPE OR PRINT NAME TRAVIS REED TELEPHONE NO. 915/683-6293

(This space for State Use)

APPROVED BY E. Villan TITLE Field Rep DATE 10/28/93
CONDITIONS OF APPROVAL, IF ANY: