

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

DEC 21 11 17 AM '83

BUR. OF. IND. MGMT
ROSWELL DISTRICT

P. O. DRAWER 10505, MIDLAND, TEXAS 79702

1650' FSL & 1980' FEL of Section 20, T-22, R-28-E

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3077' G.L.

13. STATE -
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

SUBSEQUENT REPORT

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

(Other)

(NOTE: Report results of multiple completion on W Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent proposed work. If well is directionally drilled, give subsurface location to this work). *

1. Pull rods.

2. Set C.I.B.P. at 3250'.

3. Run in hole with tubing. Set plug (30 sacks) from 3250' to 3150'

4. Pull approx. 2700' of 7 5/8" casing from hole.

5. Set plug (45 sacks) from 2750' to 2650'. (This will cover cutoff 10 3/4" casing shoe at 2705'). WOC for 4 hours. Tag TOC. (This also cover the top of the Delaware at 2600'). *Tag this plug*

6. Set plug (55 sacks) from 1100' to 1000'. WOC for 4 hours. Tag TOC

7. Set plug (55 sacks) from 440' to 340'. (This covers 16" casing shoe at 390').

8. Set marker in ~~10 sacks~~⁵⁰ cement at surface.

9. Est. date of starting this work, Jan., 1984.

18. I hereby certify that the foregoing is true and correct.

SIGNED

TITLE

ENGINEER

(This space for Federal or State Use)

(Orig. Sgd.)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

JAN 31 1984

***See Instructions on Reverse Side**