

RECEIVED BY

Form 9-331
(May 1963)

MAR 18 1985

NM OIL CONS. COMMISSION

Drawer DD

Artesia, NM 88010
(Other instructions on reverse side)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYForm approved.
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

NM 0415239 B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

AMOCO FEDERAL "AE"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 20, T-22-S, R-28-E

12. COUNTY OR PARISH 13. STATE

Eddy

New Mexico

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

DINERO OPERATING COMPANY

3. ADDRESS OF OPERATOR

P. O. DRAWER 10505, MIDLAND, TEXAS 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1650' FSL & 1980' FEL of Section 20, T-22-S, R-28-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3077' G.L.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

XX

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Pulled rods.

2. Set C.I.B.P. at 3,250'.

3. Ran in hole with tubing. Set plug (30 sacks) from 3,250' to 3,150'.

4. Set plug (45 sacks) from 2,750' to 2,650'. (This covered cut off and 10 3/4" casing shoe at 2,750'). WOC for 4 hours. Tagged cement. (This covered the top of the Delaware at 2,600').

5. Set plug (55 sacks) from 1100' to 1,000'. WOC for 4 hours. Tag top of cement at 927'.

6. Set plug (55 sacks) from 440' to 340'. (This covered 16" casing shoe at 390').

7. Set marker in 10 sacks of cement at surface.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Production Supervisor

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE

*See Instructions on Reverse Side

