ENERGY AND MINERALS DEPARTMENT				
	JIL CONSI	RVATION DI	VISE	
DISTRIBUTION	• •	O. BOX 2088	Nec. VED	Form 6-103
JANTAPE	SANTA FE	NEW MEXICO	37501	Revised ()-l-73
PILE VV				Sa. Indicate Type of Leuse
U.S.G.S.			DEC 03 '87	State 🕅 Fee
OPERATOR IN				S. State Oli & Gas Lease No.
			O. C. D.	
SUNDRY NUSE THIS FORM FOR THE FORME	NOTICES AND REPOR	TS ON WELLS	ARTESIA, OFFICE	
	•THER-			7. Unit Agreement Nume
2. Name of Operator	6. Farm or Lucase liame			
AMOCO PRODUCTION COMPAN	State "IH" Com			
3. Address of Operator	9. Well No.			
P.O. Box 4072, Odessa,	1			
4. Lucation of Well				BALDENDER CANYON
J 19	80 FEET FROM THE	South LINE AND	1980	South Rock Tank Morrow
	· · ·		· · ·	
THE East LING. SECTION	36	23-5 RANGE	24-E	
				<i></i>
	15. Elevation (Show 3873.7	, whether DF, RT, GR, o	•••.)	12. County - Eddy
1. Check App	propriate Box To Ind	icate Nature of N	otice, Report or Oth	ner Data
NOTICE OF INTI	INTION TO:		SUBSEQUENT	REPORT OF:
			(T)	<u> </u>
	PLUS AND ASAI		··· ~ ~	ALTERING CASING
TEMP68481LT ASANGON			AILLING 0705.	PLUG ANG ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS		AND CEMENT JOB	<b>F</b> -1
		******		
ФТИЕЛ				

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated dute of starting any proposed work) SEE RULE 1903.

MI and RUSU 8/31/87 and pull tubing and packer. Run 4-3/4" bit and tag at 10,226'. Drill out CIBP at 10,240' and clean out to 10,450' and pull bit. Run cement retainer and set at 10,150'. Cement squeeze perfs at 10,207'-226', 10,250'-266', 10,294'-296' and 10,342'-346' with 100 sacks of Class H. Pull tubing and WOC. Run 4-3/4" bit and drill out cement, retainer and cement to 10,225'. Run GR-CCL to check depth. Drill cement to 10,243'. Run 3-1/8" casing guns and perforate from 10,207' to 10,226' with 4 SPF. Run packer and tubing and set at 10,035'. Acidize perfs with 2000 gallons of 7.5% MS acid and 55,700 SCF nitrogen and 400 gallons of methanol. Swab well and recover load but no gas. Pull tubing and packer. Run 4" casing guns and perforate from 10,207' to 10,226' with 4 SPF. Run tubing and packer and set at 10,035'. Swab well and recover 57 barrels load water with a slight show of gas. Acidize with 3000 gallons of 7.5% MS acid, 72,000 SCF nitrogen and 600 gallons of methanol. Swab well and recover 97 bbl load water and 50 bbl new water and no gas. RD and MOSU 9/17/87. MI and RU swab unit 9/30/87 and swab 46½ hours in 6 days and recover 209 bbl water and no gas. RD and MO swab unit 10/6/87. Run pressure bomb to 10,000' on 10/23/87 and BHP 3187 psi and fluid level 3300'. MI and RUSU 11/2/87 and pull tubing and packer. Run CIBP and set at 10,180' and cap with 35' of cement. Run bit and clean out to 10,173'. Run packer and tubing and set at 9934'. Swab fluid level down to 9700'. Run 1-9/16" tubing guns and perforate from 10,075'-82' and 10,108'-17' with 4 SPF. Flow well 4 hours. RD and MOSU 11/20/87 and return well to production. (cont'd on back)

id. I hereby certify that the information above is true and complete to the best of my knowledge and belief.									
On Minnell		TITLE _	Sr. Admin. Analyst		12/01/87				
	Original Signed By Mike Williams	TITLE			DEC	4 1987			
CONDITIONS OF APPROV	AL. IF A Gil & Gas Inspector	· · · · · · ·							

17. continued from front

Prior to flow SITP 3250 psi.

PPWO: 0 BOPD, 0 BWPD, 0 MCFD PAWO: 0 BOPD, 0 BWPD, 2341 MCFD, 17/64" choke, 1900 psi flowing tubing pressure

.