

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT


OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form O-103
Revised 12-1-77

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.O.B.	
LAND OFFICE	
OPERATOR	☒



6. Indicate Type of Lease State ☒ Fee ☐
5. State Oil & Gas Lease No. L-4864
7. Unit Agreement Name
8. Form of Lease Name State IW
9. Well No. 1
10. Field and Pool, or Wildcat Dark Canyon Penn Gas
11. County Eddy

SUNDARY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (FORM O-101) FOR SUCH PROPOSALS.

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. Name of Operator
Amoco Production Company ☒

3. Address of Operator
P. O. Box 68, Hobbs, New Mexico 88240

4. Location of Well
UNIT LETTER L 1980 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 30 TOWNSHIP 23-S RANGE 25-E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)
3853' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	COMMENCE DRILLING CONS. ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOB ☐
OTHER ☐	OTHER ☐
PLUG AND ABANDON ☒	ALTERING CASING ☐
CHANGE PLANS ☐	PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1105.

Propose to plug and abandon as follows:

Call NMOCD 24 hrs. before rigging up. MISU and load well with fresh water. Release pkr., pull tbg., pkr., and tailpipe. RIH with CIBP and set above Atoka perfs at $\pm$ 9600'. Cap CIBP with 35' Class 'H' cmt. RIH with wire line and determine free point. Estimated TCMT is $\pm$ 9100'. Cut csg. 100' above 100% free point and pull csg. RIH with open ended tbg. and spot gel from 9565' to 50' below csg. cut. Spot class 'H' neat cmt. from 50' below cut. csg. to 50' above. Spot gel from top of plug to 8900' tag plug after 2 hrs. Spot 100' of Class 'H' neat cmt. from 8900' to 8800' (This will cover top of Penn) Spot gel from 7938'-6000'. Spot 100' of Class 'C' neat from 6000' to 5900'. Spot gel from 5900' to 4520'. Spot 100' of Class 'C' neat from 4520 to 4420' (This will cover top of Bone Springs). Spot gel from 4420-2222'. Spot 100' of Class 'C' neat cmt. from 2222'-2122'. (Cover intermediate csg. shoe). Spot gel from 2122-455' (tag plug after 2 hrs.) Spot 100' of Class 'C' neat cmt. from 455'-355', spot gel from 355' to within 1 jt. of tbg. from surface. Run 1 jt. tbg. and circulate Class 'C' neat cmt. to surface. Erect PxA marker and clean location.

O+5-NMOCD, A 1-J. R. Barnett, HOU Rm. 21.156 1-F. J. Nash, HOU Rm. 4.206 1-GCC

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Harry C. Clark</u>	TITLE <u>Assist. Admin. Analyst</u>	DATE <u>6/15/84</u>
APPROVED BY _____	TITLE <u>Original Signed By Leslie A. Clements Supervisor District #</u>	DATE <u>JUN 18 1984</u>
CONDITIONS OF APPROVAL, IF ANY:		