

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILZ	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

RECEIVED

DEC 16 1981

O.C.D.

ARTESIA OFFICE

Form C-103
Revised 10-1-

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	L-4682	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Farm or Lease Name State IS
3. Address of Operator P. O. Box 68, Hobbs, NM 88240	9. Well No. 1-Y
4. Location of Well UNIT LETTER E 2005 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 25 TOWNSHIP 24-S RANGE 27-E NMPM.	10. Field and Pool, or Wildcat Wildcat Delaware
15. Elevation (Show whether DF, RT, GR, etc.) 3160.7 RDB	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPMS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to revise previous procedure to plug and abandon (11-23-81) per the following (Per telecom Ellingsworth-Sexton 12-3-81).

Remove production equipment, pull rods, pump, and tubing. Go in hole with tubing and spot a 25 sack plug from 2546'-2293' across the top of the Delaware. Spot a 25 sack plug from 1901'-1649' across top of salt. Go in hole with 4" casing gun and perforate at 575' with 4 JSPF. Set cement retainer in 5-1/2" casing at 550', pump 50 sacks Class C cement to perfs at 575'. Spot a 25 sack plug on top of cement retainer from 550'-297'. Spot a 25 sack surface plug and fill casing with cement. Weld plate on casing. Erect P X A marker.

0+4-NMOCD, A 1-Hou 1-Susp 1-W. Stafford, Hou 1-DMF

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mark Freeman TITLE Assist. Admin. Analyst DATE 12-15-81

APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE DEC 18 1981

CONDITIONS OF APPROVAL, IF ANY:

Notify N.M.O.C.C. in sufficient time to witness
Plugging