

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Owner

Amoco Production Company

3. Address and Telephone No.

P. O. Box 3092, Houston, TX 77253-3092 Room 18.108

4. Location of Well (Feats. Sec., T., R., M., or Survey Description)

1980 FSL and 660 FML, Unit Letter L
Section 34, T-22-S, R-28-E

5. Lease Designation and Serial No.

NM-16331

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Cimarron/RB/Fed.Gas Com No.1

9. API Well No.

30-015-24283

10. Field and Pool, or Exploratory Area

Dublin Ranch-Atoka-Gas

11. County or Parish, State

Eddy, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐
- Notice of Intent
-
- ☒
- Subsequent Report (Org. did not incl. PxA chart)
-
- ☐
- Final Abandonment Notice

TYPE OF ACTION

- ☒
- Abandonment
-
- ☐
- Recompletion
-
- ☐
- Plugging Back
-
- ☐
- Casing Repair
-
- ☐
- Altering Casing
-
- ☐
- Other _____
-
- ☐
- Change of Plans
-
- ☐
- New Construction
-
- ☐
- Non-Routine Fracturing
-
- ☐
- Water Shut-Off
-
- ☐
- Conversion to Injection
-
- ☐
- Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent data, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

7/6/94 DIG OUT CELLAR X MIXRUSU. RTXIB X REL PKR X POH X RIH X BIT X SCRAPER X TBG TO 6100' X POH X RIH X CIBP X 965' X DRAGING X ATTEMPT TO POH X CIBP SA 776' X POH X TBG X SETTING TOOL. RIH X 6-1/4" BIT X DCS X DO CIBP X PUSH TO BOTTOM X 6240' X POH X RIH X WL GAUGE RING 6-5/16" (6.313") TO 6200' X POH X GAUGE RING X RIH X WL CIBP X SA 6030 X POH X WL X LOAD X TST CIBP X 750 PSI X OK. RIH X TBG X TAG CIBP AT 6030 X CAP CIBP X 25 SX CMT FROM 5898' TO 6030' X PULL UP TO 5898' X LOAD HOLE X 10# BRINE GEL MUD TO 2590' X PERF 2590' TO 2592' X 4 SPF X POH X WL X RIH X TBG TO 2508' X CIRC BW BETWEEN 10-3/4 CSG X 7-5/8" CSG X PMP 73 SX CMT X DISPLACE BW X 200' CMT BEHIND 7-5/8" X 200 INSIDE 7-5/8" CSG X POH X WOC. RIH X TBG X TAG CMT PLUG AT 2571' X PMP 25 SX CMT X CMT FROM 2439' TO 2511' X DISPLACE 7-5/8" CSG X MUD TO SURF X SPOT CMT PLUG X 25 SX FROM 324' TO 456' X POH X TBG X PERF FROM 200-201' X CIR CMT FROM 201' TO SURF X PMP 111 SX X CIRC 35 SX BETWEEN 7-5/8" CSG X 10-3/4" CSG X WOC. CUT OFF WELLHEAD X INSTALL PXA MARKER X FILL INCELLAR X CUT OFF DEADMEN. RDMOSU 7/13/94.

Appl. well is to be plugged and abandoned.
Locality under bond is not to be drilled until
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed Shirley M. PrinceTitle Staff AssistantDate 8/3/94

(This space for Review or Signatures)

(ORIG. SGT. JOE G. LARA

Approved by _____
Conditions of approval, if any:Title PERFECTED ENGINEERDate 8/26/94