

WORKOVER PROCEDURE: to P&ALOVING 36 STATE #1

DECEMBER 13, 1993

1. MIRU PULLING UNIT.
2. BLOW DOWN WELL, N.D. WELL HEAD N.U. 7-1/16" 3,000 PSI BOP.
3. P.U. 2-3/8" TBG. TIH TO 3,888'±. PUMP AND DISPLACE HOLE WITH 10 LB. MUD LAIDEN FLUID.
4. TOH TO 3,344', SPOT 50' CEMENT (25 SKS) PLUG.
5. TOH TO 2,310', <sup>to 2060</sup> SPOT 100' CEMENT (40 SKS) PLUG (50' BELOW 9-5/8" CSG AND 50' INSIDE CSG) S.D. 4 HRS TIH TAB PLUG.
6. TOH TO 570', SPOT 100' CEMENT (43 - SKS) PLUG (INSIDE 9-5/8" AT END OF 13-3/8" CSG).
7. TOH CUT OFF CSG HEAD, TIH SPOT 50' (22 SKS) SURFACE PLUG. INSTALL DRY HOLE MARKER.
8. SALVAGE PRODUCTION EQUIPMENT, RECLAIM WELL SITE AND ACCESS ROAD.

cc/HAL CRABB (915)686-3723  
Jerry Ball (915)686-3715