Submit 3 Corres to Appropriate District Office	Energy, Minerals and Natural Resources Department	Form C-103 Revised 1-1-89	
DISTRICT I PO DU IN HOU, M W	OIL CUNSERVATION DIVISION		
DISTRICT II P.O. Drawer DD, Artesia, NM 8	Santa Fe, New Mexico 87504-2088	30-015-24447 5. Indicate Type of Lease STATE FEE X	
DISTRICT III 1000 Rio Brazos Rd., Azlec, NN	1 87410	6. Sizie Oil & Gas Lease No.	
(DO NOT USE THIS FORM DIFFEREN	Y NOTICES AND REPORTS ON WELLS C. FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG THOM FO A IT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name	
1. Type of Well: OIL OAS WELL OTHER		Walker Fee	
2 Name of Operator Strata Productio	n Company	8. Well No. #1	
 Address of Operator P. O. Box 1030, Well Location 	9. Pool name or Wildcat Undesignated Wolfcamp		
Unit Letter I : 1980 Feet From The South Line and 990 Feet From The East Line			
		BSEQUENT REPORT OF:	
12. Describe Proposed or Compl work) SEE RULE 1103.	eted Operations (Clearly state all pertirent details, and give pertirent dates, incl	luding estimated date of starting any proposed	
9/18/92 RU Pool Well Service pulling unit.			
9/21/92 Release packer and TOH. Set CIBP at 9450'.			
9/22/92 Set 2	2/92 Set 25 sack plug at 9157'. Top of plug at 8931'.		
9/23/92 Ran f	Ran free point. SOH and LD 5 1/2" 17# S90 joints.		
9/24/92 LD 5	LD 5 1/2" casing.		
	hlumberger. Ran CBL and CEL. RU Computal 2 sidewall cores. CONTINUED	og. Ran Sidewall Core Log.	
I hereby certify that the information	above is true and complete to the best of my knowledge and belief.	Supervision 10/17/00	
SIONATURE	rol J. Darcia m. Production	Supervisor DATE <u>12/17/92</u> TELEPHONE NO. 622-1127	
(This space for State Use) OR		DEC 8 9 1992	
	THE THE TRACE IS THE TIME	DATE	

Continued

- 9/26/92 Set balance plug at 7890'.
- 9/28/92 Swab test.
- 9/30/92 Set plug at 5959'. Cemented with 200 sacks Class "C" with 2% CaCL and 200 sacks Class "C" Neat. Total 400 sacks cement. Displaced with 28 bbls fresh water for balance plug. Tag top of plug at 5154'.
- 10/05/92 Perf (22) .42 holes from 5250' to 5310'. Acidize with 1750 gal 7 1/2% NEFE with additivies. Swab test.
- 10/12/92 Perf (4) squeeze holes at 5200'.
- 10/15/92 Spot 50 sacks Metrix cement at 5238'. Squeeze 1 1/2 bbls cement in perfs.
- 10/23/92 Frac perfs from 5250' to 5310' via 2 7/8" tbg with 472 bbls 2% KCL, 35# X-link gel and 40# linear gel, 11112# 16/30 RC and 14962# 16/30 DRC with additives. Swab test.
- 10/29/92 Perf (11) .42 holes from 3804' to 3809'.
- 10/30/92 Acidize with 1000 gal 7 1/2% NEFE with additives. Swab test.
- 11/03/92 Set CIBP at 5200' and 3770' with 35' cement on top of each CIBP. Perf (27) .42 holes from 3560' to 3586' (1 spf).
- 11/04/92 Acidize with 1750 gal 7 1/2% NEFE with additives. Swab test.
- 11/07/92 Frac via 2 7/8" tubing with 120 bbls 2% KCL, 6500# 16/30 RC sand and linear gel. Swab test.
- 11/11/92 TIH with production string. PBTD 3718'.
- 11/25/92 Set pumping unit, spaced well out and hung on. Well place on test.