Submit 3 Copies to Appropriate

State of New Mexico Energ Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office OIL CONSERVATION DIVISION DISTRICT WELL API NO. P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 30-015-<u>245</u>3 Santa Fe, New Mexico 87504-2088 DISTRICT II 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 STATEXX FEE DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 LH -2392 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: New Mexico State DU WELL onner Salt Water Disposal WELL 8. Well No. 2. Name of Operator 1 Dakota Resources, Inc. 9. Pool name or Wildcat 3. Address of Operator Herradura (Delaware) Texas 79705 310 W. Wall Ste 814 Midland, Well Location 1809 _ Feet From The West _ Line and 1980 Unit Letter F : 1973 Feet From The North Line Eddy ship 22 S Range 27 E 10. Elevation (Show whether DF, RKB, RT, GR, etc.) Township 22 S **NMPM** County 3075' Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: PLUG AND ABANDON ALTERING CASING PERFORM REMEDIAL WORK REMEDIAL WORK PLUG AND ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** OTHER:_ OTHER:. 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Constructed & lined 100'x100' earthen pit. Flow well back to pit. MIRU Lucky Well Service, NU BOPE. TOOH W/ Pkr. Build extra 100'x100' pit to handle flow back. RU Black Warrior Wireline & RIH w/ 4" Csg Gun. Perf w/ 2 JSPF @ 5075'-5126', 5151-62', 5384-5420',5516-50', 5584-99' & 5621-44'. RIH w/ $\frac{1}{2}$ 7/8" PerfClean Tool and breakdown new & existing perfs using 1 bbl/ft Total intervals treated are as follows: 4988-5002', 5070-5126', 10# brine. 5140-50', 5384-5420', 5516-50', 5584-5644'. Acidize same intervals using PerfClean Tool & 5500 gals 15% NEFE Acid. RD Charger. POOH & LD workstring. MU 2 7/8" 1.812" "R" Profile, 6' 2 7/8" Pup Jt (OD-ID Plastic coated), 5 1/2" Model AL Big Bore Lok-Set Pkr (Ni Plated), 1.875" "F" Profile & On-Off Tool, & 156 jts 2 7/8" 6.50# J55 8rd EUE TBG Coated w/ Freecom Ceramkote-54. Test tbg Set pkr @ 4891.39'. Release On-Off & circ Pkr fluid in hole to 6000 psi. Latch on-off tool. RU JSI. Rih w/ slic line. in csq annulus. and complete to the fest of my knowledge and belief. DATE 05-23-96 mu: Operations Manger SKINATURE . **TELEPHONE NO 915 - 687 - 050**

This space for State Use original signed by the W. Gum DISTRICT II SUPERVISOR

"ITTLE:

JUN 0 6 1996

TYPE OR PRINT NAME

APPROVED BY