Submit 3 Copies	State of New Me Energy, Minerals and Natural Re			Form C-103 C1ST Revised 1-1-49
District Office	OU CONSERVATIC	N DIVISION	·	μ
DISTRICT J P.U. Box 1980, Hobbs, NM \$1240	OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO. 30-015-2523	
ISTRICT II Santa Fe, New Mexico 87504-2088		S. Indicate Type of		
DISTRICT III ICCU Rio Brazos Rd., Aziac, NM 87419-			6. State Oil & Gas L	SIAIE FEE X
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERCIPEIVE D (FORM C-101) FOR SUCH PROPOSALS			7. Lease Name or Unit Agreement Name	
I. Type of Well: OL OL WELL X	OTHER 1	ND 0 4007	Fort 18 Com	
2 Name of Operator	Unex ju	IAR - 8 1995	8. Well Na	
Hallwood Petroleum, Inc	Hallwood Petroleum, Inc.		1	
Address of Operator Other Goundation P. 0. Box 378111, Denver, CO 80237 D1ST. 2			9. Pool aame or Wildcal Malaga	
4. Well Location				West La
Unit Lotter :70	O_Feet From TheNorth	Line and895		he <u>west</u> Lae
Section 18	Township 245 Rs	nge <u>29E</u> DF. RKB. RT. CR. elc.1	NMPM Eddy	COUM V
	2955.8' GR			
IL Check A NOTICE OF INT	Appropriate Box to Indicate I ENTION TO:		eport, or Other I SEQUENT RE	
		REMEDIAL WORK	A	
ULL OR ALTER CASING CASING TEST AND CEMEN				
OTHER:	OTHER:			
12. Describe Proposed or Completed Opera work) SEE RULE 1103.	tions (Clearly state all pertinent details, ar	i d give pertinent dates, includ	ting estimated date of s	laring any proposed
PLEASE SEE ATTACHMENT				
	~			
•.				
I hereby certify that the information above is true	sand compiciation the best of my knowledge and	belief. Production Te		2-1-0
SIGNATURE <u>MORE OF</u>	Julan III			DATE 3-1-9
TYPE OR FRINT NAME NONYA	K. Durham			тецетноне но. 303
DISTRICT II SUI	ED BY TIM W. GUM PERVISOR			MAR 37 1995
CONDITIONS OF APPROVAL, IF ANY:	m	LE		

í

ATTACHMENT TO SUNDRY NOTICES AND REPORTS ON WELLS FORM C-103

.

1. ----

Fort 18 Com #1 Eddy County, New Mexico

Hallwood plans to recomplete this well from existing Atoka uphole to the Atoka Sands Zone following the procedures listed below on or about March 1, 1995, completing March 15, 1995.

- PROCEDURE: 1. MIRU pulling unit, NU x-over spool and BOP, test lines.
 - 2. TOH with 2 3/8" tubing and seal assembly.
 - 3. MIRU wireline unit, run gauge ring to 12,027', RIH with 4 1/2" CIBP, set at 12,010', dump 10' cement on top of CIBP. NOTE: Request an exception to the 35' of cement on CIBP rule as we need the room to perforate new zone.
 - 4. RIH with tubing and 2 3/8" by 4 1/2" packer, hydrotesting tubing to 7000#, set packer at 11,800-11,850', test backside to 1000 psi.
 - 4a. Swab tubing down to 4000-5000'.
 - 5. Perforate 11,922-30' and 11,970-76' with throughtubing HSC gun 4 spf.
 - 6. MIRU Western. Acidize perfs with 4000 gal 7 1/2% acid and ball sealers. Flow and/or swab test zone to determine productivity.

NKD95.021