DrawerbDREAU OF LAND MANAGEMENT	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)	LCO65970A 6 IF INDIAN, ALLOTTEE OR TRIBE NAME
I OIL WELL OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	8. FARM OR LEASE NAME
The Eastland Oil Company SEC.	Avalon Federal
P.O. Drawer 3488, Midland, Tx. 79702	B. WALL NO. 1 10. FIELD AND POOL OF WILDCAT
At surface	Undesignated Delaware
990' FNL and 990' FEL (NE/4NE/4)	11. SEC., T., E., M., OR BLK. AND BURVEY OR AREA
	Sec 7, T24S,R29E
	2. COUNTY OF PARISH 13. STATE Eddy New Mexic
6. Check Appropriate Box To Indicate Nature of Notice PReport, or Other Notice OF INTENTION TO:	
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	[]
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE ABANDON [®] X SHOOTING OR ACIDIZING	ABANDON MENT [®]
REPAIR WELL CHANGE FLANS (Other)	
(Other) (Not: Report results of Completion or Recompletion 7. DESCRIBE PROPOSED OR COMPLETES OPERATIONS (Clearly state all pertinent details, and give pertinent dates, in proposed work. If well is directionally drilled, give subsurface locations and memory and the subsurface locations and memory and memory and the subsurface locations are subsurface locations and memory and memory and the subsurface locations are subsurface locations and memory and memory and the subsurface locations are subsurface locations and memory and memory are subsurface locations are subsurface locations and memory and memory are subsurface locations are subsurface location	multiple completion on Well
water per hour swabbing. There were no shows of oil or gas. Casing in the well consists of:	
 a. 10-3/4" surface casing at 295' w/200 sx Class "C" cement ci b. 4²/₂" production string set in 6" hole at 2796' w/60 sx Class 	rculated. "C" cement.
 b. 4¹/₂" production string set in 6" hole at 2796' w/60 sx Class are not to TOC @ 1900'. Plugging Procedure as follows: Set CIBP in 4¹/₂" casing at 2750' w/cement dumped to 2720 2. Cut 4¹/₂" casing @ 1900' and pull casing. Using 2" tubing, circulate hole w/9.6# mud and set plug from to 1810' w/25 sx cement. Set plug from 350' to 240' w/60 sx cement and tag. Set plug from 30' to surface w/15 sx cement. Set marker and proceed w/rehabilitation of the surface. 	"C" cement. 7 <i>15⁻¹ (35⁻¹).</i>
 b. 4¹/₂" production string set in 6" hole at 2796' w/60 sx Class are not to TOC @ 1900'. Plugging Procedure as follows: Set CIBP in 4¹/₂" casing at 2750' w/cement dumped to 2720 2. Cut 4¹/₂" casing @ 1900' and pull casing. Using 2" tubing, circulate hole w/9.6# mud and set plug from to 1810' w/25 sx cement. Set plug from 350' to 240' w/60 sx cement and tag. Set plug from 36' to surface w/15 sx cement. Set marker and proceed w/rehabilitation of the surface. Work is expected to begin about October 7, 1985. 	"C" cement. 7 <i>15⁻¹ (35⁻¹).</i>
 b. 4¹/₂" production string set in 6" hole at 2796' w/60 sx Class are noted. TOC @ 1900'. Plugging Procedure as follows: Set CIBP in 4¹/₂" casing at 2750' w/cement dumped to 2720 2. Cut 4¹/₂" casing @ 1900' and pull casing. Using 2" tubing, circulate hole w/9.6# mud and set plug from to 1810' w/25 sx cement. Set plug from 350' to 240' w/60 sx cement and tag. Set plug from 350' to surface w/15 sx cement. Set marker and proceed w/rehabilitation of the surface. Work is expected to begin about October 7, 1985. 	"C" cement. 7 <i>15⁻¹ (35⁻¹).</i>
 b. 4¹/₂" production string set in 6" hole at 2796' w/60 sx Class TOC @ 1900'. Plugging Procedure as follows: Set CIBP in 4¹/₂" casing at 2750' w/cement dumped to 2720 2. Cut 4¹/₂" casing @ 1900' and pull casing. Using 2" tubing, circulate hole w/9.6# mud and set plug from to 1810' w/25 sx cement. Set plug from 350' to 240' w/60 sx cement and tag. Set plug from 35' to surface w/15 sx cement. Set marker and proceed w/rehabilitation of the surface. Work is expected to begin about October 7, 1985. I hereby certify that the foregoing is true and correct 	"C" cement. 7<i>15^{- (} 35'</i>). n 1950'
 b. 4¹/₂" production string set in 6" hole at 2796' w/60 sx Class TOC @ 1900'. Plugging Procedure as follows: Set CIBP in 4¹/₂" casing at 2750' w/cement dumped to 2720. Cut 4¹/₂" casing @ 1900' and pull casing. Using 2" tubing, circulate hole w/9.6# mud and set plug from to 1810' w/25 sx cement. Set plug from 350' to 240' w/60 sx cement and tag. Set plug from 360' to surface w/15 sx cement. Set marker and proceed w/rehabilitation of the surface. Work is expected to begin about October 7, 1985. I hereby certify that the foregoing is true and correct SIGNAL Certify for the foregoing is true and correct 	"C" cement. 7/5 ⁻⁽ 35'). n 1950' DATE <u>9-24-85</u>
 b. 4¹/₂" production string set in 6" hole at 2796' w/60 sx Class TOC @ 1900'. Plugging Procedure as follows: Set CIBP in 4¹/₂" casing at 2750' w/cement dumped to 2720 2. Cut 4¹/₂" casing @ 1900' and pull casing. Using 2" tubing, circulate hole w/9.6# mud and set plug from to 1810' w/25 sx cement. Set plug from 350' to 240' w/60 sx cement and tag. Set plug from 35' to surface w/15 sx cement. Set marker and proceed w/rehabilitation of the surface. Work is expected to begin about October 7, 1985. I hereby certify that the foregoing is true and correct 	"C" cement. 7<i>15^{- (} 35'</i>). n 1950'