Form 3160-5 UNITED (JUNE 1990) DEPARTMENT OF BUREAU OF LAND N SUNDRY NOTICES AND Do not use this form for proposals to drill or to Use "APPLICATION FOR PER	MANAGEMENT REPORTS ON WELLS	different reservoir.	FORM APPROVED Division Budget Bureau No. 1004-0135 Expires: March 31, 1993 0-52833 NM 0453201 6. If Indian, Allottee or Tribe Name
SUBMIT IN T	RIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well			
Oil Well	Gas Well	Other	8. Well Name and No. Squaw Federal # 3
2. Name of Operator Louis Dreyfus Natural Gas Corp			9. API Well No. 30-015-25379 S1
3. Address and Telephone No. 14000 Quail Springs Parkway, Suite 600	10. Field and Pool, or Exploratory Area Sheep Draw Morrow & Strawn		
4. Location of Well (Footage, Sec., T., R., M., or Survey Descri 2479' FSL & 1880' FWL	11. County or Parish, State JEddy, New Mexico		
Sec 1 - T23S - R25E Sheep Draw Morr	ow & Sheep Draw Strawn	Commingled	
CHECK APPROPRIATE BO	X(s) TO INDICATE N.		DF ACTION
TYPE OF SUBMISSION			
X Notice of Intent	Abando X Recom		Change of Plans New Construction
		ng Back	Non-Routine Fracturing
Subsequent Report	Casing	· –	Water Shut-Off
Final Abandonment Notice	·	g Casing	Conversion to Injection
	Other		Dispose Water (Note: Report results of multiple completions on Well Completion or Recompletion Report and Log Form.)

13. Describe Proposed Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled,

give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

SEE ATTACHED COMPLETION PROCEDURE AND WELL SCHEMATIC.

1600 16, 111 541 6 13, 113, 13, 13, 13, 13, 13, 13, 13, 13,	1

14. I hereby certify Signed	that the foregoing is true and correct	Title	Production Eng	Date	1/17/97
(This space for Fede Approved by	eral or State office use) (ORIG. SGD.) ALEXIS C. SWOBODA	Title	PETROLEUM ENGINEER	Date	JAN 2 4 1997
Conditions of appro	oval, if any:				

Title 18 U.S.C. Section 1001, makes it a crime for any personknowingly and willfully to make to any department or agency of the United States any false, fictious or fraudulent stateme or representations as to any matter within its jurisdiction.

LOUIS DREYFUS NATURAL GAS CORP

SQUAW FEDERAL # 3 "K" Sec 1-T23S-R25E EDDY COUNTY, NEW MEXICO

PURPOSE: Abandon the Atoka/ Morrow and complete the Strawn, if Strawn not productive, complete the Penn Lime.

- 1. MI & RU completion unit. Load tbg w/ 2 % KCL water. ND well head and NU BOP.
- 2. Release packer and TOOH w/ tubing. See schematic for details.
- 3. Set 5" OD CIBP at 10,390'.
- 4. Load casing with 2% KCL water and test casing to 1000 psi. Spot 50' cement on CIBP.

MI&RU wireline. Perforate Strawn as follows: Correlate perforations to Schlumberger CN/Litho-Den dated 10/29/85. Utilize a 4" casing gun to perforate.

Strawn	10,095 - 134' 10,187' 10,200 - 222' 10,234 - 244'	39' 1' 22' 10'	20 holes 2 hole 12 holes 6 holes
	10,280 - 306'	26'	14 holes
	10,332'	1'	2 holes
	10,373'	1'	2 holes
	10,379'	1'	2 holes
	TOTALS	101'	60 holes

- 6. TIH w/ 5" Lok-Set packer, on/off tool, w/ 2.25" "F" profile to 10,380'. Spot acid per recommendation. over Strawn 10,095 to 10,379'. Pull packer to 9970', reverse excess acid into tbg. Set packer at 9970'.
- 7. Acidize well per attached recommendation.
- 8. Swab load and put on production. If well not productive, set CIBP at 10,045' & cap w/ 50' of cement. Move to next step. If Strawn productive produce well and perform Penn Lime completion at later date.
- 9. TIH w/ 5" Lok-Set packer, on/off tool, w/ 2.25" "F" profile to 9770'. Spot 500 gals of Fer Chk II acid over Penn lime 9754 to 9770'. Pull packer to 9625', reverse excess acid into tbg. Set packer at 9625'.
- 10. Swab fluid level down to 1200' from surface.
- MI&RU wireline. Perforate Penn Sand as follows: Correlate perforations to Schlumberger CN/Litho-Den dated 10/29/85. Utilize a 2 1/8" hollow carrier perforating gun Phased at 90 degrees.

Penn Lime 9,754 to 9,770 16 ft 33 holes

- 12. Use spot acid to break down perfs if necessary and acidize well with 1500 gals Fer Chk II acid and 40 ball sealers.
- 13. Stimulate well per attached recommendation.
- 14. Swab load and put on production.



LOUIS DREYFUS NATURAL GAS CORP. WELL SCHEMATIC

