

Plug and Abandon Procedure
IMC Well No. 1
Eddy County, New Mexico

1. Morrow top 12,278', Spot 100' plug 12,328'-12,228', 45 sxs C1 H + 0.5% TF4.
2. Atoka top 11,804', Spot 100' plug 11,854'-11,754', 80 sxs C1 H + 0.5% TF4.
3. Pennsylvanian top 11,222', Spot 100' plug 11,272'-11,172', 50 sxs C1 H + 0.5% TF4.
4. 9 5/8" CS @ 9875'. Set CIBP @ 9850', cap w/25 sxs C1 H + 0.5% TF4.
5. Wolfcamp top 9505', Spot 100' plug 9555'-9455', 40 sxs C1 H + 0.5% TF4.
6. 3rd Bone Springs 9144', Spot 100' plug 9194'-9094', 42 sxs C1 H + 0.5% TF4.
7. 2nd Bone Springs 8082', Spot 100' plug 8132'-8032', 42 sxs C1 H + 0.5% TF4.
8. 6100', Spot 100' plug 6100'-6000', 35 sxs C1 C.
9. DV @ 5199', Spot 100' plug 5249'-5149', 35 sxs C1 C.
10. TOC @ 3650', Spot 100' plug 3700'-3600', 35 sxs C1 C.
11. 13 3/8" CS @ 2647'. Perf 9 5/8" @ 2697'. Spot 100' cmt (63 sxs C1 C) outside 9 5/8" & 100' cmt (35 sxs C1 C) inside 9 5/8" csg.
12. 20" CS @ 626'. Perf 9 5/8" @ 676'. Spot 100' cmt (33 sxs C1 C) outside 9 5/8" & 100' cmt (35 sxs C1 C) inside 9 5/8" csg.
13. Cut off csg. Spot 25 sxs C1 C cmt at surface. Weld on plate. Install dry hole marker.

R. Williams 3/2/87