

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN  
(Other instr.  
verse side)

PLICATE  
as on re-

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

3. LEASE DESIGNATION AND SERIAL NO.

NM 0479142

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

James E Fed.

9. WELL NO.

12

10. FIELD AND POOL, OR WILDCAT

Cabin Lake (Delaware)

11. SEC. T., R., N., OR S.E. AND  
SURVEY OR AREA

Sec. 12, T-22-S, R-30-E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Phillips Petroleum Company

3. ADDRESS OF OPERATOR

4001 Penbrook St., Odessa, Texas 79762

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)

At surface

Unit C, 660' FNL & 1980' FWL

14. PERMIT NO.

30-015-26644

15. ELEVATIONS (Show whether DP, RT, OR, etc.)

3336' KB; 3324' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Move up hole & complete

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Delaware zones (5820'-5850', 6104'-6134' & 6412'-6444') employing the "pipeline" fracture technique. Place well on pump to produce Delaware zones 5820'-6600'.

1. GIH with retrieving tool and 5-1/2" RTTS type packer on 2-7/8" tubing. Retrieve RBP at 6705'. Reset RBP to +6500'. Set packer and test RBP to 1000 psi. Dump 2 sx sand.

2. Pull up hole to ±6450'. Spot 500 gallons 20% acetic acid using 2% KCL COOH with 2-7/8" tubing and packer. NOTE - DO NOT USE KCL SUBSTITUTE AT ANY TIME.

3. Perforate 5-1/2" casing with 4" casing gun, 1 JSPF:

6412'	6422'	6432'	6442'
6414'	6424'	6434'	6444'
6416'	6426'	6436'	
6418'	6428'	6438'	
6420'	6430'	6440'	

TOTAL = 17 shots

4. GIH with 5-1/2" RTTS type packer on 3-1/2", 9.3 lb/ft, L-80 workstring with turned down collars. Set packer at +5950'.

(over)

18. I hereby certify that the foregoing is true and correct

SIGNED

*L. M. Sanders*  
L. M. Sanders

TITLE

Supervisor, Reg. Affairs

DATE

8/6/92

(This space for Federal or State office use)

Office of the Assistant Secretary

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

PETROLEUM ENGINEER

DATE

8/14/92

\*See Instructions on Reverse Side

5. Load workstring with 2% KCl. Pressure acid into Delaware perforations 6412'-6444'.
6. Swab back spent acid from Delaware perforations 6412'-6444'.
7. Reset packer to  $\pm 6350'$ . Load tubing-casing annulus with 2% KCl water.
8. Fracture treat the Delaware through perforations 6412'-6444' down 3-1/2" workstring. Frac Fluid: 25,000 gallons borate x-linked 35 lb gelled 2% KCl carrying 21,875 lbs of 20/40 mesh Ottawa Sand and 7,500 lbs of 16/30 mesh Ottawa Sand.
9. Allow well to flow until it dies. RIH with SLM and tag fill.
10. Release packer. COOH with 3-1/2" workstring and packer. GIH with 2-7/8" tubing. Clean out frac sand to  $\pm 6500'$ . COOH with 2-7/8" tubing.
11. GIH with retrieving tool and 5-1/2" RTTS type packer on 2-7/8" tubing. Set packer at  $\pm 6380'$ . Swab back load from Delaware perforations 6412'-6444'.
12. RIH with SLM and tag fill. Clean out if necessary. Release packer and retrieve RBP at  $\pm 6500'$ . Reset RBP to  $\pm 6200'$ . Set packer and test RBP to 1000 psi. Dump 2 sx sand.
13. Pull up hole to  $\pm 6150'$ . Spot 500 gallons 20% acetic acid using 2% KCl. COOH with 2-7/8" tubing and packer.
14. Perforate 5-1/2" casing with 4" casing gun, 1 JSPF:
 

6104'	6112'	6120'	6128'
6106'	6114'	6122'	6130'
6108'	6116'	6124'	6132'
6110'	6118'	6126'	6134'
TOTAL = 16 shots			
15. COOH with perforating guns.
16. GIH with 5-1/2" RTTS type packer on 3-1/2" workstring. Set packer at  $\pm 5650'$ .
17. Load workstring with 2% KCl. Pressure acid into Delaware perforations 6104'-6134' with a maximum surface pressure of 3500 psi.
18. Swab back spent acid from Delaware perforations 6104'-6134'.
19. Reset packer to  $\pm 6050'$ . Load tubing-casing annulus with 2% KCl water.
20. Acid Engineering to fracture treat the Delaware through perforations 6104'-6134' down 3-1/2" workstring. Frac Fluid: 25,000 gallons borate x-linked 35 lb gelled 2% KCl carrying 17,250 lbs of 20/40 mesh Ottawa Sand and 7,500 lbs of 16/30 mesh Ottawa Sand.
21. Allow well to flow until it dies. RIH with SLM and tag fill.