orm 3160-5 fovember 1983) Formerly 9-331) DEPARTME! OF THE IN	SUBMIT IN TRIPLICATI (Other instructions in the state of the state)	Expires August 31, 1985 5. LEASE DESIGNATION AND SESIAL NO.
BUREAU OF LAND MANAGE	MENT	NM 0479142
SUNDRY NOTICES AND REPORT (Do not use this form for proposals to drill or to deepen or Use "APPLICATION FOR PERMIT—" for	RTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL X GAS OTHER	MAR - 2 1992	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR PHILLIPS PETROLEUM COMPANY	O. C. D.	8. PARM OR LEASE NAME
3. ADDRESS OF OPERATOR 4001 Penbrook St., Odessa,	- ,	James E
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		10. FIELD AND POOL, OR FILDCAT
UNIT F, 1980' FNL & 1980' FWL		11. 88C., T., B., M., OR BLK. AND SURVEY OR ARBA Sec. 12, T-22-S, R-30-E
14. PERMIT NO. 15. ELEVATIONS (Show who		12. COUNTY OR PARISH 18. STATE
30-015-26646 3324' GL;	3335' KB	Eddy NM
16. Check Appropriate Box To India	tate Nature of Notice, Report, or	Other Data
TEST WATER SHUT-OFF PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
PRACTURE TREAT MULTIPLE COMPLETE	PRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE ABANDON®	SECOTING OR ACIDIZING	XX ABANDONMENT*
REPAIR WELL CHANGE PLANS	.	roduction XX Its of multiple completion on Well
(Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all p	Completion or Recor	ipletion Report and Log form.)
/2/92 RU DDU. GIH w/drill collars & 4- /3/92 Tag DV tool @ 5970'. Drill out & /7/92 Perforate 5-1/2" casing w/4" casi 7556', 7558', 7560'. GIH w/ 5-1/ packer @ 7504'. /8/92 Acidize perforations 7546'-7560'	clean out to 7675'. ng gun 7546', 7548', 75 2" RTTS packer, 2-7/8" (50', 7552', 7554', workstring. Set
-9-	,	
15-92 Swabbing back load.	totale DD 0 market	Cat =1 0 75201 Dull
/16/92 Release packer & COOH. GIH w/ re up @ set packer. Test plug to 50 /20/92 Spot 420 gal. acetic acid. COOH gun 1 JSPF 7394', 7400', 7404', 7 7486', 7492', 7498', 7504', 7510'	00 psi. Release packer w/ workstring & packer. '444', 7450', 7456', 746	& drop 2 sk sand on plug. Perforate w/4" 2', 7468', 7474', 7480',
Set packer & RU to swab.	7394'-7510' w/2000 gal	7_1/2% NFFF
/21/92 Swab well. Acidize perforations 7394'-7510' w/2000 gal. 7-1/2% NEFE. /24/92 Release packer & GIH to 7530'. Release BP & COOH.		
/27/92 Fracture treat well w/46000 gal. resin coated 10/30 mesh sand.	polyemulsion, 135000# 2	0/40 mesh sand & 56000#
1/28/92 Flowing back load. 1/30/92 GIH w/5-1/2" RTTS packer on 2-7/8 پر VER	B" workstring. Set pack	er @ 7348'. RU to swab.
18. I hereby certify that the threesthy is true and correct	Supervisor Regulati	on & 2/24/92
SIGNED / M Sanders (915) 368-	Supervisor, Regulation Proration	n DATE 2/24/92
(This space for Federal or State office use)		
APPROVED BY TITLE		DATE
CONDITIONS OF APPROVAL, IF ANY:		2 7 1992
*See Instru	octions on Reverse Side	50S

2/1-13/92 Swabbing. 2/14/92 GIH w/ tbg., rods and pump. 2/15/92 Pumped 2.5 BO & 1.5 BW.

Pumped 60 B0 & 257 BW. 2/19/92

Temp. drop from report pending production stablization and potential test.